

U. S. Department of Agriculture

FOREST SERVICE

BR-9

chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 N. R. 26W 4th P. Mer.

Meander Corner common to Sections

4, and 5 (N. bank)

Corner consists of a Ash stake (XX) in place


State condition good

Dimensions above ground 3x3x24 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species R. pine. Stump

Diameter 24"

Bearing N50E

Distance 0.40 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Seth W. Peterson

(Signature)

Jr. Asst. to Tech.

(Title)

3/1/38

(Date)

B-I stamp is very rotten and most of the wording is gone. In spite of the fact that the GLO notes call for a white instead of a red pine, the location with reference to B.C. 4-5-32-33 leads me to believe that it is genuine.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of **Hallroad Grads-Dist. 1.25 mi.**

tree inches diameter, on the **South**

Metal Location Poster is on a **ash**



(Make sketch of topography near Corner)

T. 56N. R. 26W. 4th P. Mer.

U. S. Department of Agriculture
FOREST SERVICE

13-C-9

Rangers copy

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 53 R. 26 Mer. 4

Meander corner Corner common to Sections 4, 5, and _____

Corner consists of a Decayed Pole Pt. (not) in place
State condition Rotted off at ground

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

B.T.			
------	--	--	--

Species W. Pine stump

Diameter 24"

Bearing N 5 E

Distance 45 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Old decayed pole point 8" under water and mud.


O. Linnau
(Signature)

7/13/1936
(Date)

Jr. Foreman
(Title)

Metal Location Poster is on a W. Birch tree 6 inches diameter, on the East side of line from which this Corner bears 45 links chains-distant. Give any further facts which will aid in finding this Corner again.

A small creek crosses an old railroad grade one chain east of the meander corner.



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

Handwritten scribbles and initials in the top right corner.

~~Alameda~~ NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 30 R. 30 Mer.

~~Header corner~~ Corner common to Sections 4, and _____

Corner consists of a _____ (not) in place
State condition otted off at ground.

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

<u>B-2</u>			
------------	--	--	--

Species 3. Pine stump

Diameter 24"

Bearing E 30°

Distance 45 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? old decayed pole point B

under water and mud.

Arnon Jones
(Signature)

7/17/1918

(Date)

W. J. Jones
(Title)

(Title)

A small oval object on
old railroad grade was found
of the railroad corner.

Corner again.

Give any further facts which will aid in finding this


as it is some distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

Superior
copy

U. S. Department of Agriculture
FOREST SERVICE

B-C 9

Mississippi NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58 R. 26 Mer. 4

Header corner Corner common to Sections 4, 5, and



Corner consists of a Decayed Pole Pt. (not) in place State condition Rotted off at ground.

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



B.T.

Species W. Pine stump

Diameter 24"

Bearing N 5 E

Distance 45 links

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? old decayed pole point 3" under water and mud.


O. Linnell (Signature)

Dr. Foreman (Title)

7/13/1938 (Date)

Corner again:
A small creek crosses an
old railroad grade one chain east
of the rounder corner.

Give any further facts which will aid in finding this
corner again:
45 Links from which this Corner bears
side of
1300 inches diameter, on the
tree
Metal Location Poster is on a
W. H. Hersh



(Make sketch of topography near Corner)