

U. S. Department of Agriculture  
FOREST SERVICE

P-5 P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N R. 26W 4 P. Mer.

1/4 Corner common to Sections 19, and 20

Corner consists of a Cedar stake (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S		S
	19		20
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? <sup>Yes</sup> Yes

If not, why? I believe it has been offset.

from its proper place i.e. center of road.

Found iron pipe in center of road.

George H. Jennings

(Signature)

8-21-35 (Date)

Const. Foreman C & M (Title)

Intersection of old roads.  
*of*

Corner again.

Give any further facts which will aid in finding this


chains distant. 0.36

from which this Corner bears N9W

side of tree

tree 4 inches diameter, on the N

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

T. 59N R. 26W 4 P Mer.

U. S. Department of Agriculture  
FOREST SERVICE

P-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59N. R. 26W. 9<sup>th</sup> Mer.

1/4 Corner common to Sections  
20, and 21

Corner consists of a W. cedar post (not) in place

State condition good "iron pipe"

Dimensions above ground post 32" pipe 12 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S.20		S.21

N W S E


NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	S.20		S.21
	B.T.		B.T.

Species N. pine N. pine  
 Diameter 7" 10"  
 Bearing S.28°W. S.59°E.  
 Distance 43 links 22 links

Do you believe this to be a genuine Land Office Corner? No

If not, why? County resurvey cor.

Ernest Perry  
(Signature)

5-14-35  
(Date)

Field Ass't  
(Title)

Corner again.

Give any further facts which will aid in finding this


~~291m~~ distant.

from which this Corner bears *N. 59° W.*

side of *tree*

tree *10* inches diameter, on the *N.W.*

Metal Location Poster is on a *N. P. 100*



(Make sketch of topography near Corner)

T. 39N R. 26W 4th Mer.

## U. S. Department of Agriculture

## FOREST SERVICE

f-9

Chippewa NATIONAL FOREST

## CORNERS OF THE PUBLIC SURVEY

T. 54 R. 26 4<sup>th</sup> Mer.1/4 Corner common to Sections  
20, and 21Corner consists of a W. Cedar Post (not) in place  
State condition good 1" iron pipeDimensions above ground Post 3 1/2" pipe 12" inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	S. 20		S. 21
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and  
fill blanks below, giving bearings from Corner to Trees and  
Distances in Links.

	S. 20		S. 21
	B. T.		B. T.

Species \_\_\_\_\_ N. Pine \_\_\_\_\_ N. Pine.  
 Diameter \_\_\_\_\_ 9" \_\_\_\_\_ 10"  
 Bearing \_\_\_\_\_ 228 W \_\_\_\_\_ 559 E  
 Distance \_\_\_\_\_ 43 lks. \_\_\_\_\_ 29 lks.

Do you believe this to be a genuine Land Office Corner? No  
 If not, why? County Resurvey Cor.

Ernest Perry

(Signature)

Field Ass't.

(Title)

5/14/35  
(Date)

Corner again.

Give any further facts which will aid in finding this


29 1/2 chains distant.

from which this Corner bears N. 59 W.

side of trees

tree 10 inches diameter, on the N.W.

Metal Location Poster is on a N.P.



(Make sketch of topography near Corner)

T. R. Mer.