

Form 874-S—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

13

NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 60 R. 27 4 Mer.

Sec Corner common to Sections  
9, 10, 15, and 16

Corner consists of a old post (not) in place  
State condition Fair

Dimensions above ground 30 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? No bearing trees probably established by CCC's.


H. Hamelain  
(Signature)

12-19-39  
(Date)

CCC  
(Title)

Corner again.  
 Follow old 1199th road east  
 approx. 12 miles from  
 Chassis.

Metal Location Poster is on a  
 tree inches diameter, on the  
 side of  
 from which this Corner bears  
 chains distant.  
 Give any further facts which will aid in finding this



(Make sketch of topography near Corner)