

U. S. Department of Agriculture

FOREST SERVICE

L-1

CHIPPENAW

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 25 5 Mer.

Corner common to Sections 13, 14, 16, 18, and

Corner consists of a post in place

State condition poor

Dimensions above ground 15 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species None

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No.

If not, why? County Corner

RAYMOND T. DEFANT

(Signature)

Jr. Civil Engineer

(Title)

1-2-40

(Date)

Corner post decayed off at ground
Corner again.

Give any further facts which will aid in finding this
chain distant.

0.47

from which this Corner bears

N 60° E

side of


Corner

tree 6 inches diameter, on the

S.W.

Metal Location Poster is on a

Ash



(Make sketch of topography near Corner)

T. 141 R. 25 Mer. 2-1