

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

A-11  
 Posted  
 2/11/40

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 27 5 Mer.

$\frac{1}{4}$  Corner common to Sections

(4), and 33

Corner consists of a brass cap (364) in place

State condition good

Dimensions above ground 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 33		S 4	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{4}$ S4			
B.T.			

Species Tam. (dead)

Diameter 6"

Bearing S69°W

Distance .81

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*R. T. Defaut*  
 Raymond T. Defaut  
 (Signature)

Jr. Civil Engineer  
 (Title)

8/2/40

(Date)

at edge of black brush

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 141 R. 4-11 Mer.