

U. S. Department of Agriculture  
FOREST SERVICE

X-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 191 N R. 21 + 30 W 5th Mer.



1/4 Corner common to Sections  
31, and 36

Corner consists of a Iron Pipe & Cap (not) in place  
State condition Good

Dimensions above ground 18 inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Apparently set by  
County Engineer.

Arthur J. Johnson

(Signature)

12/16/37  
(Date)

Eme Field Marker  
(Title)

X-1

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears *S. 80° E.*

side of *Tree*

tree inches diameter, on the *50th West*

Metal Location Poster is on a *Aspen*



(Make sketch of topography near Corner)

*T. 141N R. 9430W 57E Mer. X-1*