

U. S. Department of Agriculture

FOREST SERVICE

*Chippewa* *Forest* *E-19*  
NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 141 R. 29 5 Mer.

1/4 Corner common to Sections

2, 11, and 11

Corner consists of a G. I. O. Brass Cap (not) in place

State condition Good

Dimensions above ground 10" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

2		11	
---	--	----	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

	None		

Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

4-9-35  
(Date)

*H. W. Coaker*  
(Signature)  
*E. Sumner*  
(Title)

*E-19*

Continued from page 1

Corner again.  
A 34' located  
Highway N. of the cor.

Give any further facts which will aid in finding this


38745 chains distant

from which this corner bears N. 45° E

side of 1/4 cor

8" inches diameter, on the S.W

Metal Location Poster is on a  
Date



(Make sketch of topography near corner)

Mer. E-19

T 141 R 29 S