

Form 874-9—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

*POSTED*

*Chippewa* NATIONAL FOREST *E 11*

CORNERS OF THE PUBLIC SURVEY

*T. 141 N. R. 31 W. 5<sup>th</sup>* Mer. Quarter Corner common to Sections

\_\_\_\_\_, \_\_\_\_\_, *4*, and *9*

Corner consists of a *Iron pipe* (not) in place  
State condition *Good*

Dimensions above ground *2' x 1 1/2"* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<i>None</i>			
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>None</i>			

Species *None*

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *No*


If not, why? *Established by County Surveyor*

*Dorman J. Latton*  
Mar. 11, 1935 *Engineer*  
(Date) (Signature) (Title)

Dashed lines for notes.

Corner again.

Give any further facts which will aid in finding this chains distant. from which this Corner bears side of tree inches diameter, on the Metal Location Poster is on a



(Make sketch of topography near Corner)

T. L. H. N. R. 31 W 57 E Mer.