

U. S. Department of Agriculture
FOREST SERVICE

Posted
12/11/40
N17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 27 Mer. 5

Section Corner Corner common to Sections
14, 15, 22, and 25

Corner consists of a post ~~mark~~ in place

State condition poor

Dimensions above ground loose inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
| | | | |

N W S E

| | | | |
|--|--|--|--|
| | | | |
| | | | |

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
| | | | |

Species oak _____

Diameter 24" _____

Bearing N20°E _____

Distance 40 lks. _____

Do you believe this to be a genuine Land Office Corner? no

If not, why? County Corner

Raymond T. DeFaut
(Signature)

Jr. Civil Engineer
(Title)

10/17/40
(Date)

CONCRETE FOUND ON CORNER - SECTION 110
SECTION 110

Corner again.

Give any further facts which will aid in finding the

chain's distant.

From which this Corner bears

side of

tree - inches diameter, on the

Metal Location Posters on a

