

U. S. Department of Agriculture  
FOREST SERVICE

✓10-11

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 142 R. 27 S. 5 Mer.

M.C. Corner common to Sections

28, and 33

Corner consists of a brass cap (not) in place

State condition good

Dimensions above ground 6" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S.		S.	
28		37	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

M.C.	M.C.		
S. 28	S. 33		
B.T.	B.T.		

Species Tamarack Tam. Stump

Diameter 7" 7"

Bearing N10°W S64°E

Distance .32 .23

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*R. T. Defant*  
Raymond T. Defant  
(Signature)

Jr. Civil Engineer

(Title)

6-17-40

(Date)

Corner again. **Good**

Give any further facts which will aid in finding the **92** **chaine distant.**

from which this Corner bears **South**

side of **Tree**

tree **20** inches diameter, on the **East**

Metal Location **Poster** is on a **Color**

