

U. S. Department of Agriculture  
FOREST SERVICE

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *142 N.* R. *31 W.* *5th* Mer.

*North 1/4* Corner common to Sections  
(*T142 R32*), *S12*, and *7*

Corner consists of *iron pipe* (not) in place

State condition *fair*

Dimensions above ground *2 x 2 1/2* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<i>None</i>		
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species *None*

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? \_\_\_\_\_

*County resurvey corner*

*Dormand Sutton*  
(Signature)

*3-15-35*  
(Date)

*Engineer*  
(Title)

Poster  
Corner again.  
North of road


Give any further facts which will aid in finding this

8.20 chains distant.

from which this Corner bears south

side of tree

Metal Location Poster is on an Aspen tree 5 inches diameter, on the south



(Make sketch of topography near Corner)

T/411N R 51 + 32W 5th Mer. F-1