

U. S. Department of Agriculture

FOREST SERVICE

*Chippewa* NATIONAL FOREST

X-5  
A

CORNERS OF THE PUBLIC SURVEY

T. *142 N.* R. *31 W.* Mer.

*14* Corner common to Sections

*31*, and *32*

Corner consists of a *2 I.P.* (not) in place

State condition *Good*

Dimensions above ground *16* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species *None*

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? *No*

If not, why? *County Corner*

*Carl E. Steadland*  
(Signature)

*Foreman*  
(Title)

*4/20/1937*  
(Date)

Corner again.


Give any further facts which will aid in finding this

from which this Corner bears *150' NE*

side of

tree inches diameter, on the

Metal Location Poster is on a *White Oak*



(Make sketch of topography near Corner)

T. J. H. N. R. 31 M. 5 H. X-5 M. 5