

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ¹⁴³~~142~~ R. 26 S. 5 Mer.

^{1/4} Corner common to Sections

31, 6, and

Corner consists of a (not) in place
State condition There is no post

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4			
BT			

Species Cedar Cedar

Diameter 10 8

Bearing N13°E S32°W

Distance 13 lks. 20 lks

Do you believe this to be a genuine Land Office Corner? NO

If not, why? Scars right age

one BT rotted and damaged

but ties in o.k.

Raymond T. Defant

(Signature)

7-29-41 Agric. Aide Foreman CCC SP-5

(Date)

(Title)

T. 143&142 R. 26 5 Mer.

(Make sketch of topography near Corner)

Sec.	Sec. 3/
	T 143 N.
Sec.	Sec. 6
	T 142 N

Metal Location Poster is on a
tree inches diameter, on the
side of
from which this Corner bears
..... chains distant.

Give any further facts which will aid in finding this
Corner again.

Cedar swamp. Old cuttings around
corner. 4 chains and along town
line east of lake.