

U. S. Department of Agriculture
FOREST SERVICE

V-9

V-9
Packed
12/11/18

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 Mer. 5

Section Corner common to Sections
28, 29, 32, and 33

Corner consists of a (not) in place
State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

NW SW SE NE

Mound of is located

 Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and
fill blanks below, giving bearings from Corner to Trees and
Distances in Links.

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

| | | | |
|------|--|--|--|
| B.T. | | | |
|------|--|--|--|

Species Tam. stp.

Diameter 10"

Bearing N39°W

Distance 58 ft.

Do you believe this to be a genuine Land Office Corner? no

If not, why? County Corner

R. T. DeFaut
Raymond T. DeFaut

(Signature)

Jr. Civil Engineer

(Title)


10/23/40

(Date)

V-9

to examine these woods
to the other end of the road
Corner again.

Give any further facts which will aid in finding this
chairs distant.
from which this corner bears
side of
tree - inches diameter, on the
Metal Location Poster is on a



(Make sketch of topography near corner)