

U. S. Department of Agriculture

FOREST SERVICE

A-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 143 R. 27 5th Mer. A17

Section Corner common to Sections

34 9 3 5, T. 144-27, and
2 3, T. 143-27
Corner consists of a Brass cap (set) in place

State condition Good

Dimensions above ground inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Stanley M. Morrison


(Signature)

acting Dist. Ranger

(Title)

3/24/60
(Date)

A-17



(Make sketch of topography near Corner and show section line marks thus "X")

T. 144 R. 27
 143 27
 Mer. A-17
 5 27
 5 27

Metal Location Poster is on a *Bank* tree 7 inches diameter, on the *SW* side of *tree* from which this Corner bears *S. 45.0 W. 30 ft* (Bearing) (Distance) and is on Section line marker between Secs. _____ and _____ on the _____ (Tree, post, etc.) _____ (Name of road, trail, etc.) located chains *R., W., N., S.,* from Sec. Cor.; $\frac{1}{4}$ Cor.; Witness Cor. (Cross out nonapplicable)
 Give any further facts needed to find Corner again:
This line poster was of corner