

Form 874-8—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

G-25

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 143 R. 28 5 Mer.

E-1 Corner common to Sections  
Sec. 12, and

Corner consists of a not found (not) in place  
State condition


Dimensions above ground inches  
Sketch grooves, letters, figures, or notches, on proper face or edge.  
CARDINAL POSITION DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Birch

Diameter 12"

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why? not found

Ray De Fant

Ray De Fant  
(Signature)

Jr. Civil Eng.  
(Title)

11-30-39  
(Date)

Corner again. Could not find corner--must be in center-line of road


Give any further facts which will aid in finding this chains distant.

from which this Corner bears

side of Boy River Road

tree 12 inches diameter, on the West

Metal Location Poster is on a Birch



(Make sketch of topography near Corner)

6-25