

U. S. Department of Agriculture  
FOREST SERVICE

219

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 194N. R. 27W. 5th P. Mer.

1/4 Corner common to Sections  
26, and 35

Corner consists of a 1" iron pipe (not) in place


State condition Good

Dimensions above ground 2" x 12" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species T.477. T.477.

Diameter 5" 5"

Bearing S06°30'E N38°W

Distance 2.91chs. 1.99chs.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

E. M. Handy  
(Signature)

1/19/38  
(Date)

(Title)

U. S. Department of Agriculture

Location Poster on Fireway  
#2 off Chas. Lyons's Road  
on Sec line 25936 13 due  
East of this corner.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near corner)