

U. S. Department of Agriculture
FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 144 R. 29 Mer.

Section Corner common to Sections

Corner consists of a wood post & iron pipe (not) in place

State condition good

Dimensions above ground pipe - 8 in. post 4 8 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S 36			A.P. S 2 S 1		S 2	S 1	
---------	--	--	-------------------	--	--------	--------	--

N W S E NW SW SE NE

Mound of pipe cap is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T 144
R 29
S 1

[Blank Box]

T 144
R 29
S 2

[Blank Box]

B.T.

[Blank Box]

B.T.

[Blank Box]

Species Birch Cedar

Diameter 8 in. 18 in.

Bearing S 32° E S 10° W

Distance 45 lks. 64 lks.

Do you believe this to be a genuine Land Office Corner? YES

If not, why?

A. Friesen


(Signature)

1/16/36

(Date)

(Title)

(Make sketch of topography near Corner)



Metal Location Poster is on a *FLM*

tree *6* inches diameter, on the *N-E*

side of *tree*

from which this Corner bears *N. 39 E.*

0.25 chains distant.

Give any further facts which will aid in finding this

Corner again.