

U. S. Department of Agriculture

FOREST SERVICE

T-3

*Chippewa* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 52 Mer.

1/4 Corner common to Sections 30, and

Corner consists of a metal tag (not) in place


State condition good

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No


If not, why? no evidence

*Stanley M. Morrison*  
(Signature)

9-12-60  
(Date)

*Forestry aid*  
(Title)

(Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a *Red Pine* tree  $\frac{1}{2}$  inches diameter, on the *North* side of *line* from which this Corner bears *50* (Bearing) *20 ft* (Distance) and is on

Section line marker between Secs. and

a on the (Tree, post, etc.) (Name of road, trail, etc.) located chains E, W, N, S, from Sec. Cor.;  $\frac{1}{4}$  Cor.; Witness Cor. (Cross out nonapplicable)

Give any further facts needed to find Corner again:

*Also note to W. corner of Sec. 13. Can be seen from W. Bank of - It is about 1/2 mi. S from Pt. to corner of Section*