

U. S. Department of Agriculture  
FOREST SERVICE

B-8

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 27 5<sup>th</sup> Mer.

~~111E~~ Corner common to Sections  
5, \_\_\_\_\_, and \_\_\_\_\_

Corner consists of a metal tag (not) in place



State condition good

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

STONE CORNERS

METAL CORNERS



N W S E

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes


If not, why? No evidence

J. M. Morrison  
(Signature)

July 1960  
(Date)

Forestry and  
(Title)

T. 145 R. 27 S. 2 Mer.  
 (Make sketch of topography near Corner and show section line markers thus "X")



Metal Location Poster is on a Redwood tree 6 inches diameter, on the North side of the from which this Corner bears 0 (Bearing) and 0 (Distance) is on Section line marker between Secs. and is on a 2 (Tree, post, etc.) on the (Name of road, trail, etc.) located chains 1, W, N, S, from Sec. Cor.; 1/4 Cor.; Witness Cor. (Cross out nonapplicable) Give any further facts needed to find Corner again: Black Pine Lumber Co. E & C. J. corner