

Form 874-9—Revised May, 1918  
U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 145 R. 26 & 27 5 Mer.

1/4 Corner common to Sections

31, and 36

Corner consists of a wooden stake (not) in place

State condition Rotten at ground line

Dimensions above ground 24 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

I/4 S		I/4 S	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

I/4 S			

Species J.P.

Diameter 12"

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? Yes.

If not, why? \_\_\_\_\_

\_\_\_\_\_

\_\_\_\_\_

Signature.

Date. Title. 8-3027


T. 140

R. 26 & 27

5

Mer.

(Make sketch of topography near Corner.)



Metal Location Poster is on a

tree \_\_\_\_\_ inches diameter, on the

side of \_\_\_\_\_

from which this Corner bears \_\_\_\_\_

\_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this

Corner again.

PSIP on section line 9.76 chains

South of the corner.