

E5

Patched

D. Maddy
O. Hattie

T 147 R. 25 5 P.M.

SEC. corner common
to sections 5, 6, 7, and
8
Corner stack not found.

SEC. 6

B.T.

SPECIES - H. MAPLE

DIA. 16"

BEARING

DIS.

Original

Summary

Use only

2 1/2"

SEC. 5

B.T.

SPECIES W. PINE STUMP

DIA. 30"

Exact location of site
on telephone pole bearing
road. 40 links south
of bearing tree on
section 6.

