

Form 874-0—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

E-13

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 27W S3P Mer.

Section Corner common to Sections  
 3, 4, 9, and 10

Corner consists of a Tam Post (not) in place  
 State condition Good

Dimensions above ground 30. inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

T148N R27W S4	T148N R27W S9	T148N R27W S10	T148N R27W S3
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T148N R27W S3			
B. T.			

Species Tam  
 Diameter 2.99  
 Bearing N59°01'E  
 Distance 0.49

Do you believe this to be a genuine Land Office Corner? No  
 If not, why? To Recent

10/15/35 (Date)  
 Arthur H. Jager (Signature)  
 Chief of Party (Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

*N 50° W*


side of

*Trees*

tree 2 inches diameter, on the

*Cedar NW*

Metal Location Poster is on a



(Make sketch of topography near Corner)

E-13

Mer.

*S 41° E*

*T. 148 N. R. 27 W.*

U. S. Department of Agriculture

FOREST SERVICE

P  
E13

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 27W 5th Mer.

Section Corner common to Sections

3, 4, 9, and 10

Corner consists of a Tamarack post (not) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

T148N	T148N	T148N	T148N
R27W	R27W	R27W	R27W
S 4	S 9	S 10	S 3

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T148N R27W S 3			
B. T.			

Species Tamarack

Diameter snag

Bearing N 59° E

Distance 0.49 chains.

Do you believe this to be a genuine Land Office Corner? No.

If not, why? Corner placed too recently.

A. H. Gayer

(Signature)

Oct. 10, '35

(Date)

Chief of Party.

(Title)

Corner again.  
Give any further facts which will aid in finding this


chains distant. 0.06

from which this Corner bears N 50° W

side of tree

tree 2 inches diameter, on the NW

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)