

Form 874-B—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

V21  
 P

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 148N R. 27W 5th Mer.  
 Section

Corner common to Sections 26, 25, 35, and 36

Corner consists of a Spr. Post (Not) in place  
 State condition Poor.


Dimensions above ground 28 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.  
 \* CARDINAL POSITION DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species	P.m.	Cedar	
Diameter	12"	10"	
Bearing	3 85°	78°	
Distance	.91	.68	Chains

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

*W. Emmert*

(Signature)

Chief of party.

6/5/75


(Date)

(Title)

-----  
-----  
-----  
-----  
-----

Corner again.  
B. T. in poorer condition. Corner  
is not inscribed. Corner located  
on side of Alder brush swamp

Give any further facts which will aid in finding this  
chain distant.  
68  
from which this Corner bears N 80° W  
side of Sec. 26  
tree 6 inches diameter, on the SE  
Metal Location Poster is on a Balsam



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

V-21

CORNERS OF THE PUBLIC SURVEY

T. 148 R. 27 5th Mer.

Section Corner common to Sections  
26, 25, 35, and 36

Corner consists of a Spv Post (not) in place



State condition Rock

Dimensions above ground 28" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N. W. S. E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

US US			
BT	BT		

Species Tam Cat

Diameter 12" 10"

Bearing S85E N78W

Distance 191 68

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Donald Riger  
(Signature)

6-5-35  
(Date)

Chief of Party  
(Title)

Corner again.  
BT in poor shape Cor. 15  
not in sec. had Cor. 25  
W side of Aid Creek Swamp

Give any further facts which will aid in finding this  
chain distant.  
from which this Corner bears  
side of  
tree 6 inches diameter, on the  
Metal Location Poster is on a

N 80° W

Sec 26

SE

B6  
B6

Sec 36

Sec 35

Sec 25

Sec 26

(Make sketch of topography near Corner)

Mer.

R.

T.