

U. S. Department of Agriculture  
FOREST SERVICE

521

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148N R. 29W 5th Mer.

Section Corner common to Sections  
11, 12, 13, and 14

Corner consists of a Elm (not) in place

State condition Old Corner Rotted - Set New

Dimensions above ground 40" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

sec 11	sec 12	sec 13	sec 14
NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

sec 14			
BT			

Species Elm

Diameter 10"

Bearing S-40°W

Distance 114k

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

Merrin Balke  
(Signature)


Aug 26 - 1936  
(Date)

Leader  
(Title)

49

Corner again.  
 Corner is located on South side  
 of Logging Road, which starts  
 from County Road running N-S-  
 At N.E. Corner Sta. 13-T148N  
 729 W

Give any further facts which will aid in finding this  
 11 LKS. ~~obvious distant.~~  
 from which this Corner bears  
 5-40° W  
 side of **Bearing Tree**  
 tree 12 inches diameter, on the  
 North  
 Metal Location Poster is on a Elm



(Make sketch of topography near Corner)

T. 148 N. R. 89 W. 274 Mer.