

U. S. Department of Agriculture

FOREST SERVICE

V-23  
V-23

*Section 36* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148* R. *31* Mer. *5th*

Corner common to Sections *35*, and *36*

Corner consists of a \_\_\_\_\_ (not) in place State condition \_\_\_\_\_

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>BT</i>			

Species *Cedar* \_\_\_\_\_

Diameter *12* \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? \_\_\_\_\_

If not, why? *But looks like orig. BT*

\_\_\_\_\_

(Signature)

(Date)

(Title)

Metal Location Poster is on a  
 tree inches diameter, on the  
 side of  
 from which this Corner bears  
 chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

R.

T.

V-23  
 Mer.  
 V-23