

T142N R30W CORNER RESTORATION

T142N R30W
CORNER RESTORATION



FIELD BOOK


820012

BOOK 5

DISTANCES FROM SIDE STAKES FOR CROSS-SECTIONING

Roadway of any Width. Side Slopes 1½ to 1.

In the figure below: opposite 7 under "Cut or Fill" and under .3 read 11.0, the distance out from the side stake at left. Also, opposite 11 under "Cut or Fill" and under .1 read 16.7, the distance out from the side stake at right.



Cut or Fill	Distance out from Side or Shoulder Stake										Cut or Fill
	0	.1	.2	.3	.4	.5	.6	.7	.8	.9	
0	0.0	0.2	0.3	0.5	0.6	0.8	0.9	1.1	1.2	1.4	0
1	1.5	1.7	1.8	2.0	2.1	2.3	2.4	2.6	2.7	2.9	1
2	3.0	3.2	3.3	3.5	3.6	3.8	3.9	4.1	4.2	4.4	2
3	4.5	4.7	4.8	5.0	5.1	5.3	5.4	5.6	5.7	5.9	3
4	6.0	6.2	6.3	6.5	6.6	6.8	6.9	7.1	7.2	7.4	4
5	7.5	7.7	7.8	8.0	8.1	8.3	8.4	8.6	8.7	8.9	5
6	9.0	9.2	9.3	9.5	9.6	9.8	9.9	10.1	10.2	10.4	6
7	10.5	10.7	10.8	11.0	11.1	11.3	11.4	11.6	11.7	11.9	7
8	12.0	12.2	12.3	12.5	12.6	12.8	12.9	13.1	13.2	13.4	8
9	13.5	13.7	13.8	14.0	14.1	14.3	14.4	14.6	14.7	14.9	9
10	15.0	15.2	15.3	15.5	15.6	15.8	15.9	16.1	16.2	16.4	10
11	16.5	16.7	16.8	17.0	17.1	17.3	17.4	17.6	17.7	17.9	11
12	18.0	18.2	18.3	18.5	18.6	18.8	18.9	19.1	19.2	19.4	12
13	19.5	19.7	19.8	20.0	20.1	20.3	20.4	20.6	20.7	20.9	13
14	21.0	21.2	21.3	21.5	21.6	21.8	21.9	22.1	22.2	22.4	14
15	22.5	22.7	22.8	23.0	23.1	23.3	23.4	23.6	23.7	23.9	15
16	24.0	24.2	24.3	24.5	24.6	24.8	24.9	25.1	25.2	25.4	16
17	25.5	25.7	25.8	26.0	26.1	26.3	26.4	26.6	26.7	26.9	17
18	27.0	27.2	27.3	27.5	27.6	27.8	27.9	28.1	28.2	28.4	18
19	28.5	28.7	28.8	29.0	29.1	29.3	29.4	29.6	29.7	29.9	19
20	30.0	30.2	30.3	30.5	30.6	30.8	30.9	31.1	31.2	31.4	20
21	31.5	31.7	31.8	32.0	32.1	32.3	32.4	32.6	32.7	32.9	21
22	33.0	33.2	33.3	33.5	33.6	33.8	33.9	34.1	34.2	34.4	22
23	34.5	34.7	34.8	35.0	35.1	35.3	35.4	35.6	35.7	35.9	23
24	36.0	36.2	36.3	36.5	36.6	36.8	36.9	37.1	37.2	37.4	24
25	37.5	37.7	37.8	38.0	38.1	38.3	38.4	38.6	38.7	38.9	25
26	39.0	39.2	39.3	39.5	39.6	39.8	39.9	40.1	40.2	40.4	26
27	40.5	40.7	40.8	41.0	41.1	41.3	41.4	41.6	41.7	41.9	27
28	42.0	42.2	42.3	42.5	42.6	42.8	42.9	43.1	43.2	43.4	28
29	43.5	43.7	43.8	44.0	44.1	44.3	44.4	44.6	44.7	44.9	29
30	45.0	45.2	45.3	45.5	45.6	45.8	45.9	46.1	46.2	46.4	30
31	46.5	46.7	46.8	47.0	47.1	47.3	47.4	47.6	47.7	47.9	31
32	48.0	48.2	48.3	48.5	48.6	48.8	48.9	49.1	49.2	49.4	32
33	49.5	49.7	49.8	50.0	50.1	50.3	50.4	50.6	50.7	50.9	33
34	51.0	51.2	51.3	51.5	51.6	51.8	51.9	52.1	52.2	52.4	34
35	52.5	52.7	52.8	53.0	53.1	53.3	53.4	53.6	53.7	53.9	35
36	54.0	54.2	54.3	54.5	54.6	54.8	54.9	55.1	55.2	55.4	36
37	55.5	55.7	55.8	56.0	56.1	56.3	56.4	56.6	56.7	56.9	37
38	57.0	57.2	57.3	57.5	57.6	57.8	57.9	58.1	58.2	58.4	38
39	58.5	58.7	58.8	59.0	59.1	59.3	59.4	59.6	59.7	59.9	39
40	60.0	60.2	60.3	60.5	60.6	60.8	60.9	61.1	61.2	61.4	40

BOOK #5

30	29			28
26	25	23		24
		22		
		21		27
7	6			5

USFS, CASS COUNTY, MISSOURI



The paper in this book is made of 50% high grade rag stock with a WATER RESISTING surface sizing.

KEUFFEL & ESSER CO.

* See Pages 56 thru 70 for Episcopal Cemetery,
Catholic Cemetery and Episcopal Church Tracts

	6	5	4	3	2	1
	7	8	9	10	11	12
	18	17	28 29 30 26 25 23 24	15	14	13
			22 21 20 19 18 17 16			
	19	20	14 13 12 11	22	23	24
			46			
		55 52 54 51 50 49	4 * 1 2 3			
	30	45 28	42 28	27	26	25
		44 50 47				
	39	38 37 36 34 35				
		75 33				
	78	77 76 74 73 71 72	33	34	35	36
		79 78 77 76 75 74 73 72				

The Birches.

5-9,10

Angle Point 3 of Allotment 1340 and Angle
Point 4 of Allotment 1313 Sec. 28

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked S28

10/24/89 GB MEH-CK AP 4 AP 3

FD. IRON AND CAP - IN PLACE TR TR

IN GOOD CONDITION - 12" ABOVE 1313 1340

GROUND - IN OAK & BIRCH TR 1584

PINE TO NE - NOW MKD TO 1918

CLEAR CUT

MKD NEW BT'S.

W. OAK 10 S78W 78.30' MKD S28 BT

N. PINE 18 N38E 129.30' MKD AP3 S28 BT

N. PINE 14 N79E 71.23' MKD AP3 S28 BT

8' steel sign posts west 3.0' and
north 3.1' from corner with signs att.
Line to S. west & north. C.C. Donegan

CHAINED 657.4' MEASUREMENT GOOD - LINE AT

S89E FELL 50' TO NORTH OF COR.

LINE SHOULD RUN S85E

BLUE LINE NW OF AP

S-1/0

North West 1/16 Cor. Sec. 28

G. L. O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass

cap marked

NW 1/16 S28

2/24/89 CK, GB, MEH - Fd. GLO iron 1918

pipe with brass cap set 9" above ground in place.

Poplar 7" N3°45'E 126 IKS - 83.16'

Fd. a stump hole at bring & dist.

N. Pine 8" N25³/₄°W 84 IKS - 55.44'

Fd. N. Pine 23 N26W at 55.44' Scar visible

Fd. on 458 on 12" Aspen S13°E - 1650 FT

5680-11 by Gardner 1963

10/24/89 MKd. New BT'S:

N. Pine 17" S65W 98.4' NW 1/4 S28BT

W. OAK 10" N1E 54.4' NW 1/4 S28BT

1/22/90 CK, GB

Placed 8" steel sign posts south 3.05'

and east 3.10' with both signs attached

Line to standard goes southeast

from corner.

CC Done 1992

Chained S85E 657' from Angle Point. Distance
and bring was good.

S-10, 11

Angle Point 6 of Allotment 1726 Sec. 28

G.L.O. Resurvey notes of 1918

Iron post 3 long 1" diam. with brass cap marked

10/24/89 CK, MH, GB

S 28

Found 610 iron pipe

TR 1340

with brass cap set 4"

AP 6

above the swamp. Iron

TR

pipe is pitted.

1726

1/22/90 CK, GB

Placed 8' steel sign post south 3.05'
west 3.05' and north 3.15' with
both signs attached for reference object.

This area is in fluence by Wabongon lake.
High water at certain times.

Line to standard goes south + west from corner.

10/24/89 Chained from NW 1/6 east to this
corner. Distance checked good.

Corner falls out in a Ash swale approx. 150'
west and south to high ground. \pm 75'
east to high ground. C.C. Done 1992

R-9, 10

Special Meander Cor. Between Allotments 1313
and 1340 Sec. 28

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap marked

SMC	
TR	TR
1313	1340
S 28	S 28
T142N	R30W
1918	

12/12/89 GB CK

FD. IRON & CAP - IN PLACE - STANDING UPRIGHT AT EDGE
OF DEAD TAM & CEDAR AND EDGE OF POND NW-SE
4" BELOW WATER TO TOP OF CAP

PLACE 8' STEEL SIGN POST SOUTH EDGE OF CAP

24" HIGH - VERY SOFT BOTTOM

Placed F.S.L.P. on 10" Tam. snag S27W 9.6'

54-9 also on this tree.

Line to standard goes south

4
12/12/89 - Chained from angle pt. 344
north to this corner. Fd. dist checked
good. Lake is flooding over corner.

N-12

East 1/16 Col Secs. 16-21

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked S 16

1/20/64 Found GLO E1/16

iron pipe with S 21
brass cap. 1918

Pine 12" N57 1/2° E 84 1/3 - 55.44'
1/20/64 Found 20 Red Pine N61° E 55.44'

Pine 6" S48° E 146 1/3 - 96.36'
1/20/64 Found 17" Red Pine S45° E 97.3

Form 458 on 8" ASPEN S32° E - 112.86 FT

SEE RESTORATION CERTIFICATE BY
MEYERS 1/20/64. HAVE NOT BEEN
ABLE TO LOCATE FIELD BOOK NOTES.
DATA ON CERT - 4/19/78 MGS

10/30/85 GB JA

Fd: 1" x 3" brass lapped Iron Pipe 5" under
water, placed steel sign post 2' x 6" on
west side of Brass Cap both signs attached
Fd BTS:

N. Pine	18"	S45 E	97.3'	scribe visible	} splcs tag red ring
N. Pine	20"	N61 E	55.44	scribe visible	
marked W. Pine	25"	S74 E	55.8' E 1/2 S 21 AT.		

possible GLO TREE cut down (stump with
axe marks) Next to NE BT - dist & bearing
similar

Corner falls on East side of Beaver
marsh 20' west of High ground

cc done 10/85

N-11

Quarter Cor. Secs. 16-21

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked

$$\begin{array}{r} \pm 516 \\ 4 \hline \end{array}$$

S 21

1918

Pine 32" N22 $\frac{3}{4}$ °E 38 1K5 - 25.08'

NOW 34" W. PINE AT N23E - 25.08'

Oak 6" S43 $\frac{1}{4}$ °W 75 1K5 - 49.50'

NOW DECAYED OAK STUMP S43W 49.50'

SEE RESTORATION CERTIFICATE BY
MEYERS, 1/23/64. HAVE NOT BEEN
ABLE TO LOCATE FIELD BOOK NOTES.

DATA ON CERT., 4/18/78 M.S.

INFORMATION FROM CERTIFICATE

1/23/64

Ed. GLO 1" IRON POST - IN PLACE

MARKED NEW BT'S.

W. OAK 9 S27 $\frac{1}{2}$ °W 81.35' MKD 1/4 S16 BT

R. OAK 10 N79°W 69.9' MKD 1/4 S21 BT

72" SIGN POST WEST 4.7' BOTH SIGNS

West 1/16 Cor. Secs. 16-21

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked

W 1/16 516

S 21

1918

Poplar 4" S 38 $\frac{3}{4}$ ° E 7 1/2 - 4.62'

Dak 4" N 50 $\frac{3}{4}$ ° W 20 1/2 - 13.20'

Form 458 on 8" ASPEN S 32° E - 11.22 FT

4
6
2

Center $\frac{1}{4}$ Sec. 21

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass

Cap marked C $\frac{1}{4}$ S21

1918

Poplar 6" N69 $\frac{1}{2}$ $^{\circ}$ E 42 KS - 27.72'

Poplar 12" N72 $\frac{3}{4}$ $^{\circ}$ W 92 KS - 60.72'

Form 458 on 14" ASPEN North - 6.60 FT


No date

0-11

Center North 1/16 Cor. Sec. 21

G. L. O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap marked



Poplar 6" N52°E 12 IKS - 7.92'

NO TRACE OF BT AT N52E 7.9'

Poplar 7" S4°N 16 IKS - 10.56'

NO TRACE OF BT AT S4N 10.56'

SEE RESTORATION CERTIFICATE BY MEYERS, 1/21/64. NOT ABLE TO LOCATE FIELD BOOK NOTES - SEE CERT FOR DATA. 4/19/78 - WES

INFORMATION FROM CERTIFICATE

1/21/64

FD. GLO 1" IRON - IN PLACE

MARKED NEW BT'S.

DAK 6 N70W 38.92' MKD CN'1/16 S21 BT

DAK 12 S1E 69.75' " CN'1/16 S21 BT

72" STEEL POST EAST 4.0' BOTH SIGNS

Angle Point 4 of Allotment 1360 and Angle
Point 1 of Allotment 1359 Sec. 21

G. L. O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass
cap marked

AP4

TR

1360

AP1

TR

1359

1918

Center East 1/16 Cor. Sec. 21

G. L. O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass
Cap marked

E 1/16
C ————— C

S 21

1918

Pits 18 x 18 x 12" East and West of Cor.
6' dist.

P-10, 11

Angle Point 3 of Allotment 1358 Sec. 21

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked

AP 3

TR

1358

TR 1359

1918

SEE RESTORATION CERTIFICATE BY
MEYERS 1/21/64. NOT ABLE TO
LOCATE FIELD BOOK NOTES. SEE
CERT. FOR NOTES.

NOTE:

CERT. MAY HAVE A TYPING ERROR
OR MONUMENT IS STAMPED WRONG
OR 1918 NOTES ARE IN ERROR IN
THE #'s of ALLOTMENTS. IS
IT 1357, 1358 or 1359?

INFORMATION FROM CERTIFICATE 7/18/78

1/21/64

Ed. GLO 1" IRON - IN PLACE

MARKED NEW BT'S.

N. PINE 10 N29E 66.7' MKD APBT

N. PINE 11 S20W 41.2' " APBT

72" STEEL POST EAST 4.7'

P-10

Center West 1/16 Cor. Sec. 21

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked

W 1/16
C ————— C

S 21

1918

Pine 5" S 70° E 41 1/2 - 27.66'
1/21/64 Found 14" Red Pine at bring + dist.

Pine 5" N 35 1/4° W 60 1/2 - 39.60'
1/21/64 Found 11" Red Pine at bring + dist.
Form 458 on 6" Aspen N 48° E - 14.52 FT

SEE RESTORATION CERTIFICATE BY
MEYERS 1/21/64. COULD NOT LOCATE
FIELD NOTES TO SUPPORT THIS CERT.

SEE CERT. FOR DATA. 4/18/78 ~~MSA~~
Information from certificate - 1/21/64

Found GLO iron pipe with brass cap set

Found remains of both GLO BT's.

Rescribed both GLO BT's.

Set 72" sign post north 40 with both

P-9, 10

Angle Point 5 of Allotment 1355 Soc. 21

G.L.O. Resurvey notes of 1918

Iron post 3/4 long 1" diam. with brass cap
marked

AP 5

TR

1355

1918

SEE RESTORATION CERTIFICATE BY
MEYERS 1/21/64. COULD NOT LOCATE
FIELD NOTES TO SUPPORT THIS CERT.
SEE CERT FOR DATA. 4/18/78 MMS

INFORMATION FROM CERTIFICATE

1/21/64

FD. GLO 1" IRON - IN PLACE

MARKED NEW BT'S.

N. PINE 14 N39W 87.0' MKD. AP BT

N. PINE 11 S20E 23.3' " AP BT

72" STEEL POST - NORTH 4.65' BOTH SIGNS

North East 1/6 Cor. Sec. 21
 G.L.O. Resurvey notes of 1918
 Iron post 3' long 1" diam. with brass
 cap marked NE 1/6 S 21
 1918

Poplar 5" 559¹/₄° W 10 IKS - 6.60'

Poplar 6" N 48° E 10 IKS - 6.60'

South West 1/16 Cor. Sec 21

G.L.O Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked

SW 1/16 S 21

1918

Poplar 9" N20°W 35 1/2 - 23.10'

Poplar 7" N79°E 24 1/2 - 15.84'

0-10

North West 1/16 Cor. Sec. 21

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked

NW 1/16 S21

1918

Poplar 6" S17³⁰E 40 IKS - 26.40'

NOW ASPEN STUMP SZE 26.4'

Poplar 5" S25⁰W 44 IKS - 29.04'

NOW ASPEN STUMP SZSW 29.06'

SEE RESTORATION CERTIFICATE By
MEYERS 1/22/64. NOT ABLE TO
LOCATE FIELD BOOK NOTES. SEE CERT.
FOR DATA. 4/18/78 - MES

INFORMATION FROM CERTIFICATE

1/22/64

FD. GLO 1" IRON - IN PLACE

MARKED NEW BT'S.

N. PINE 10 N85W 19.1' MKD NW 1/16 S21 BT

W. PINE 11 N35E 41.25' " NW 1/16 S21 BT

72" STEEL POST SOUTH 4.15' BOTH SIGNS

Angle point 3 of Allotment 1360 and Angle
Point 2 of Allotment 1359 Sec. 21

C.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked

TR

1360

TR AP 3

1355 AP 2

TR

1359

1918

Angle Point 2 of Allotment 135 B Sec. 21

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked

IR 1359

AP 2

TR

1358

1918

0-9/10

Angle Point 4 of Allotment 1355 Sec. 21

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked

AP 4

TR

1355

1918

SEE RESTORATION CERTIFICATE BY
MEYERS 1/22/64. NOT ABLE TO
LOCATE FIELD NOTES - SEE CERT.
FOR DATA, 4/18/78 MSS

INFORMATION FROM CERTIFICATE

1/22/64

FD. GLO 1" IRON - IN PLACE

MARKED NEW BT'S.

OAK 7 SITE 15.2' MKD AP BT

OAK 11 NZE 28.44' " AP BT

72" STEEL POST - EAST 4.4' BOTH SIGNS

M, N-11

21

Angle Point 3 of Allotment 411 Sec. 16

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap marked

	TR
TR	1411
1360	AP3.

1918

SEE RESTORATION CERTIFICATE BY
MEYERS, 1/13/64. NOT ABLE
TO LOCATE FIELD BOOK NOTES
FOR THIS CORNER. SEE CERT. FOR
DATA. MES 4/18/78

Information from certificate - 1/13/64

Fd. GLO iron pipe in place

Marked New BT'S:

Red Pine 22" S74W 63' ^{Scribed} AP BT

Oak 10" S9½W 56.15' AP BT

72" steel post east 40' with both signs

M-11

Center South 1/16 Cor. Sec. 6

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap marked

C
S 1/16 S 16

C

1918

Poplar 8" N40³⁰°E 38 IKS - 25.08'
1/23/64 Now a stump at bearing + distance

Poplar 10" N42°W 96 IKS - 63.36'
Now a stump at bearing + distance.

SEE RESTORATION CERTIFICATE BY
MEYERS 1/23/64 - I HAVE NOT
BEEN ABLE TO LOCATE FIELD
NOTES ON THIS CERT. - SEE CERT.
FOR DATA. *MES* 4/18/78

Information from certificate - 1/23/64

Found GLO 1" iron pipe with brass cap.

Found GLO BT evidence:

Mark new BTS:

Oak 9" S52¹/₂°W 51.1 ^{scribed} CS 1/16 BTRed Pine 10" N67¹/₂°E 73.3 CS 1/16 S 16 BT

Set 72" steel post south 4.6' with both signs

Center $\frac{1}{4}$ Sec. 16

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked


C $\frac{1}{4}$ S16

1918

Tamarack 7" N8°E 14 KS - 9.24'

Poplar 9" N36 $\frac{1}{4}$ °W 58 KS - 38.28'

Center East 1/16 Cor. Sec. 16
 G.L.O. Resurvey notes of 1918
 Iron post 3' long 1" diam. with brass cap
 marked



S 16
 1918

Poplar 8" N 17° E 42 1/2 KS - 27.23'

W. Oak 14" S 57 1/2° W 25 1/2 KS - 16.50'

Center West 1/16 Cor. Sec. 16

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked W 1/16

8/21/89 G. BRAMA, R. MAIN C — C

Found GLO iron pipe S 16
with brass cap in place. 1918

Brass cap set 8" above grassy mat.

Pits 18 x 18 x 12" East & West of Cor.

3' dist. Pits have been over-run by
meadow grass.We busted iron pipe by trying to
drive monument down. Iron pipe with
brass cap is about 18" long. Needs
sign post for support

1/23/90 CK, GB

Set a 3" aluminum mkd. cap on a 3/4" x 8"
alum. rod to mark the center west 1/16position. Placed GLO irons T142WR30W
with cap on north side of W 1/16
new monument. Set reference objects: C — S 16 C
U.S.F.S.Set 8' steel sign posts north 40'
and west 40' with both signs attached
line to standard north & west. No trees
near for BT's. C.C. Done 1992

Need sign posts for monumentation

8/21/89 Chained N39E 644' from Angle Point 394
Distance checked good. Corner falls in meadow
grass approx 250' east of woods.

L-9,10

Angle Point 3 of Allotment 1363 and
Angle Point 4 of Allotment 1344 Sec. 16
G.L.O. Resurvey Notes of 1918

Iron post 3' long 1" diam. with brass
cap marked

	TR	TR
8/21/89 R. MAIN, G. BRAMA	1344	1363

Found GLO iron pipe	AP 4	AP 3
---------------------	------	------

with brass cap set TR 1274

firmly in the ground. 1918

Brass cap set 7" above ground.

Mkd. BT'S:

W.OAK 14" S 21 E 9.55 S 16 BT

W.OAK 11" S 42 W 25.62 S 16 BT

W.OAK 12" N 85 W 37.65 AP 4 S 16 BT

2/5/90 CK, GB, R.D.

Placed 8' steel sign posts east and west
4.0' from corner.

LINE TO STANDARD EAST + WEST C.C. Done 1992

8/21/89 Chained from 1/4 corner N 89 E, 644'
Found corner at distance and bearing

Angle Point 4 of Allotment 1411 Sec. 16

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam with brass cap
marked

AP4

TR

1411

TR

1374

1918

10/30/85 JA 6B

Fd: 1" x 3" Brass Capped Iron Pipe up 6"
marked OK

Steel Signpost 2"x1" South 3.7' Both signs

N. Pine 12" N 32 W 32.0' overgrown

N. Pine 14" S 60 E 26.9' overgrown

Mkd. New BT

N. Pine 19" S 13 W 62.10' AP 516 BT

spks

tags

red ring

Corner falls in Pine - clear cut East

Charred South 662 to corner from SE 1/4

cc done 10/85

North East 1/16 Cor. Sec. 16

C.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap marked

NE 1/16 S16

1918

Pits 18 x 18 x 12' East and West of Cor.
6' dist.

K-10

North West 1/16 Cor. Sec. 16

G.L.O. Resurvey notes of 1918

Iron post 3/8 long 1" diam. with brass cap
marked 8/21/89 G. BAAMA ^{R. MAIN} NW 1/16 Sec. 16

Found GLO iron with brass 1918

cap set in place. Brass cap set 8" above ground.

Pits 18 x 18 x 12" East and West of the
Cor. 6' dist. Found evidence of both pits.

1/23/90 CK-GB

Set Reference objects:

8" steel sign posts west 4.1' and
south 4.0' with both signs attached.

No trees near.

Line to standard west & south. ^{cc Dow} 1992

29
8/21/89 Chained N88E, 644' from Angle Point 1,244
Brqing & distance good. Corner falls in grass
meadow. Very dry condition today.

Need 8 sign posts for monumentation

K-9, 10

Angle Point 2 of Allotment 1363, Angle Point
1 of Allotment 1344 and Angle Point 4 of
Allotment 1733 Sec. 16

G.L.O. Resurvey notes of 1918

Iron post 3' long 1" diam. with brass cap
marked

8/21/89 G. Brama, R. Main

TR

1733

Found G.L.O. iron with

AP4

brass cap set firmly

AP1

AP2

in the ground. Brass

TR

TR

cap set 18" above ground. 1344

1363

Iron pipe is badly pitted.

1918

5680-2 by Gardner early 1960's

8/21/89 Mkd. BT's:

W.OAK 15° N65 E 33.45 516 BT

Ash 10" 553 E 33.70' AP2 516 BT

W.OAK 15° S 8 W 57.55 AP1 516 BT

8" STEEL SIGN POSTS 4.0' NORTH + 4.0' EAST

LINE TO STANDARD NORTH + EAST

C.C. Done 1992

30

8/21/89 Chained N88E from approx. NW 1/6 bet sec's 16, 17
624'. Fell 16' feet short of G.L.O. distance. Need
to look for NW 1/6 16' west of approx. position.
Chained from this Angle Point N88E 644'.
Found NW 1/6 of sec. 16 at bearing & dist.
This angle point falls in a ash swale, oak and
popple. A N-S woods trail is approx 500'
west of corner.

South 1/16 Cor. Secs. 31-32

G.L.O. Resurvey notes of 1917

Iron post 3/4 long 1" diam. with brass cap marked

S 1/16

S 31 S 32

1917

Oak 3" S 45³/₄° E 72 1/2 - 47.52'

Oak 10" N 80° W 64 1/2 - 42.24'

32 X-5

Quarter Cor Secs. 31-32

B.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

	4	
S31		S32

1917

W. Oak 6" N39 $\frac{1}{2}$ °E 127 lks - 83.82'

W. Oak 6" S62°W 169 lks - 111.54'

5680-11 by Gardner - 1964

3-12-81 B. Olson Monument OK

3 new Bts

9' W. OAK N88°E 2423' MKD. $\frac{1}{4}$ S32 BT

11" W. OAK S2°E 4882' " $\frac{1}{4}$ S32 BT

10" R. OAK S88°W 6023' " $\frac{1}{4}$ S31 BT

LINE to STD. RUNS N & W

9-24-02 R. MAIN

FD IRON up 104 FT LEANS NORTH. CORNER IN

MIXED HARDWOODS. CORNER IS 75 FT N26W

OF Y IN WOODS ROADS. HEAVY STEEL SIGN

POSTS 400 FT WEST 3.9 FT NORTH. Bts OK.

DIFFERENTIAL LAT 47°04'27.882
CORRECTED GPS LONG 94°30'47.743

W-5

North $\frac{1}{16}$ Cor. Secs. 31-32

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

N $\frac{1}{16}$

S.31 S.32

1917

W. Oak 9" S36°E 29 IKS - 19.14'

N. Pine 12" N19 $\frac{1}{2}$ °W 117 IKS - 77.22'

5680-11 by Gardner - 1964

3-12-81 B. Olson Monument Bent South

2 new Bts

10" R. Oak N79°E 4256' MKD. N $\frac{1}{16}$ S32 Bt

8" Basswood N58°W 28.40' " N $\frac{1}{16}$ S31 Bt

Line to std. runs South

V-5

Sec. Col. Secs. 29-30-31-32

C.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

T142N R30W

S30 S29

S31 S32

1917

Mound of stone 2' base 15' high, West of Col.

5680-11 by Wittkeft & Cney 1965

1-15-81 B. Olson Monument Dent to N.

4 New Bts

8" W.OAK S66°W 20.00' MKD. T142N R30W S31 Bt

7" Birch N65°W 44.25 " T142N R30W S30 Bt

16" R.PINE N59°E 103.90' " T142N R30W S29 Bt

9" W.OAK S47°E 57.10' " T142N R30W S32 Bt

Line to Std. Runs WEST

CC DONE

34

4/28/93 C. Krause R. Maen

Found 1981 monument tipped over and under
 drift beam, pushed out by Cass County. Replaced
 2 ft monument with a 2½" x 48" galvanized
 steel pipe with 3" brass cap stamped T142N R30W
 1981 bearing trees are still good.

S30 S29

S31 S32

Witnessed By: (New)

1993
USFS

W.OAK 9" N29°W

113.65 ft MKD: S30 Bt
0 ft to SPK Double Blazed.

CEDAR POST 4x4 WEST 8.02 ft to nail

8 ft steel sign post 4.0 ft east 3.7 ft north

West 1/16 Cor. Secs. 29-32

G.L.C. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

W 1/16 ——— S 29

S 32

1917

W. Oak 7" N33°E 39 KS- 25.74'

W. Oak 8" S40½°W 340 KS- 224.40'

V-4

East 1/16 Col. Secs. 30-31

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

S30

E 1/16

S31

1917

Birch 4" S56 $\frac{1}{2}$ °W 37 1X5 - 24.42'

5680-11 by Wittkopf & Emery - 1965

1-14-81 B. Olson monument OK

3 NEW Bts

14" OAK N8°E 28.86' MKD. E 1/16 S30BT

9" OAK S50°W 68.85' " E 1/16 S31BT

8" OAK S78°E 63.80' " E 1/16 S31BT

V-3,4

Angle Point 2 of Allotment 1692 and Angle

Point 1 of Allotment 1222 Sec. 31

C.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

API	AP2
TR	TR
1222	1692
1917	

1-15-81 B. Olson Monument OK

3 NEW Bts

14" ASPEN 556°E 17.52' MKD AP2 Bt

9" OAK 511°W 19.86' " API Bt

8" Birch 572°W 13.38' " API Bt

Quarter Cor. Secs. 30-31

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

$\frac{1}{4}$ 530

531

1917

Poplar 5" S55°E 62 KS - 40.92'

W. Oak 4" N56¹⁰°W 79 KS - 52.14'

West 1/16 Cor. Secs. 30-31

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam with brass cap marked

W 1/16 S 30

S 31

1917

Pine 5" N 28 1/2° W 76 1/2 - 50.16'

Oak 3" S 25 1/2° W 14 1/2 - 9.24'

Center Quarter Cor. Sec. 32

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

C $\frac{1}{4}$ S32

1917

No Accessories available

Angle Point 1 of Allotment 1407 Sec. 32

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

API

TR

1407

S32

1917

South East 1/16 Cor. Sec. 32

G.L.O. Resurvey notes of 1917

Iron post. 3' long 1" diam. with brass cap
marked 12/16/92 Krause & Brana SE 1/16 S. 32

Fd. GLO iron with brass cap 1917

set in the ground. Pipe leaning some. O.C. up 6"

B. Lak 5" N69 $\frac{1}{2}$ ° E 252 1K5 - 166.32'

Fd. 12" Red OAK N70E at 163.5 with lower scar.

Poplar 5" S29° E 174 1K6 - 114.84'

Didn't look for poplar.

Another Red OAK^{10"} was N70E at 166.5 but
had no scar. May have to cut into these
Red OAKs and look for scribe.

Placed a old fence post alongside GLO
iron. Placed a F.S.L.P. on 13" R. OAK,
N26W at 19.75 to BOD spike.

12/16/92 - Chained from E 1/16 at N1E 1285'
Distance and line checked real good.

Angle Point 4 of Allotment 1407 Sec. 32

G. L. O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

AP 4

TR

1407 S 32

1917

U-5
 South 1/16 Cor. Secs 29-30

G.L.C. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

S 1/16

S30 S29

1917

R. Oak 10" S37°E 25 KS - 14.50'

W. Oak 12" S65°W 120 KS - 79.20'

2-2-81 B. Olson Monument OK. No Bts

3 new Bts

8" W. OAK N76°W 36.61 MXD. S 1/16 S30 Bt

9" R. OAK S29°E 23.50 " S 1/16 S29 Bt

8" R. OAK S84°E 34.95 " S 1/16 S29 Bt

Line to Std Runs East

T-5

Quarter Cor. Secs. 29-30

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

$$\begin{array}{c} \frac{1}{4} \\ \hline S 30 \quad | \quad S 29 \end{array}$$

1917

Tamarack 6" N49 $\frac{1}{2}$ °E 42 IRS-27.72'

Tamarack 6" S55°W 14 IRS-9.24'

1-6-81 B. Olson

Monument OK No Bts.

3 NEW Bts

10" TAM. S85°W 15.42 MXD. $\frac{1}{4}$ S80 BT6" TAM. S21°W 52.05 " $\frac{1}{4}$ S30 BT19" OAK N70°E 267.09 " $\frac{1}{4}$ S29 BT

STEEL post w/signs 4' N & W

LINES to Standard N & W

Meander Cor. Secs. 19-30

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

T 142 N R 30 W

MC

S 19

S 30

1917


R. Dak 16" S 43 $\frac{1}{2}$ ° E 71.185 - 46.86'

R. Dak 9" N 66° E 103.185 - 62.98'

Center South 1/16 Cor. Sec. 29

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked



Mound of stone, 2' base, 13' high, west of Cor.

Center Quarter Sec. 29

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

C 4 S 29

1917

W. Pine 12" N $15\frac{3}{4}^{\circ}$ E 28 lks - 18.48'

Poplar 10" N $79\frac{1}{2}^{\circ}$ W 142 lks - 93.72'

Center North 1/16 Cor. Sec. 29

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

C
N 1/16 | S 29

C
1917

N. Pine 24" N 68⁺° E 136 lxs - 89.76'

NOVA DECAYED PINE STUMP 12" HIGH WITH CHOP MARKS
FACING CORNER

Pine 12" N 110° W 42 lxs - 27.72'

7/9/86

USED METAL DETECTOR AND HAVE DRAW UNDER

BLACKTOP ON WEST EDGE OF N+S COUNTY ROAD

1' E OF WHITE EDGE LINE ON BLACKTOP - RED X

7/10/86 CK JA TF

Dug this position: Fd. Brass lapped Iron Pipe
top bent 1' to the SE down 4' in road - could not
straighten - left as found; set 4' Brass capped Iron
pipe 1/2" below road surface ^{on top of and} at center of GLO Iron.
This position fits GLO BT (N. Pine) and survey
measurements in this area.

CC.

7/86

7/16/86 CK-JA-GB

MINO BRASS CAP

down 2" in tar surface

T142N R30W

C
N 1/16 | S 29

C


1986

USFS

WITNESSED BY "

N. PINE 13" N 35W 141.85' } Blazed & scribed
N. PINE 18" N 74 E 73.65' } spks, tags,
W. PINE 32" S 76 W 98.10' } red paint

Corner falls 11.2' west of $\frac{1}{4}$ of County Rd 13
and down township rd 30 west on north edge



South West 1/16 Cor. Sec. 29

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

SW 1/16 Sec. 29

1917

Oak 5" N43½°E 58.1Ks- 38.28'

Oak 16" S23°W 67.1Ks- 44.22'

2-2-81 B. Olson Monument OK

3 new Bts

No Bts

10" ROAK S66°W 39.25' MKD. SW 1/16 S29 Bt

11" R.OAK S6°W 33.35' " SW 1/16 S29 Bt

7" Birch S E 17.05' " SW 1/16 S29 Bt

Line to std. runs West

North West 1/16 Cor Sec. 29

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

NW 1/16 S 29

1917

Oak 12" N17½° W 91KS - 5.94'
in road

Maple 8" N47° E 50 KS - 33.00'
falls in yard

7/8/86 CK JA

Corner was reported near top of surface, being hooked by grader in town road. Ed Thue took us to this location - we found hole where iron was supposed to be - tied out this pt. Set up traverse from N 1/16 to Ap. 304 to CN 1/16 to prove out location. These pts. are G.L.O. iron pipes. Distance to the west fits within 1' and line within .10' and projected east, line and distance checks also. No evidence of G.L.O. Bearing trees but these recent survey measurements prove out location. Set 1/2 pellet down 10" in road surface - will return to remonument after road construction

7/16/86 - CK, JA, GB

Electric Pole N35W 43.82

Telephone
Utility Pole S65W 55.5

OKC
7/86

Special Meander Col. Sec. 29 (S. bank Agency Bay)

G.L.D. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

~~SMC~~
S.29 S.29

1917

Poplar 6" S14°W 6 1/2' 3.96'

Poplar 5" S39°E 18 1/2' 11.88'

Angle Point 3 of Allotment 1585 and Angle
Point 4 of Allotment 1565 Sec. 29

G. L. O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

AP 4	AP 3
------	------

TR	TR
----	----

1565	1585
------	------

S29

1917

7/8/86 CK JA

No evidence of GLO iron pipe from road
activity - Fd Smydein position for this corner
from plat recorded at Cass County which is 1" pinched
iron pipe down 2" in road - left as found
dist. and line fits pretty good.

cc
7/86

5-5-6

Angle Point 3 of Allotment 1574 and Angle Point
4 of Allotment 1573 Sec 29

C.L.C. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

AP 4	AP 3
------	------

TR	TR
----	----

1573	1574
------	------

S 29

1917

7/8/86 CK-JA

FD. GLO IRON IN PLACE CAP IS MISSING - NOW IS

6" BELDW ROAD - 2' NORTH OF CENTER LINE

TIES

W. OAK 12 S 23 E 51.00' SPIKE + TAG

FISH 10 S 48 E 44.75' SPIKE + TAG

LOT IRON 1" N 36 E 40.00' STAKE NEXT TO PIPE

FENCE LINE E+W IS 24.2' SOUTH OF CORNER

54

ck
7/8/86

Special Meander Cor. Sec. 29 (S. side Agency Bay)

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

~~SMC~~
S 29 S 29

1917

Poplar 7" S10°E 103.1K5 - 67.98'

Poplar 8" S15°W 23.1K5 - 15.18'

Angle Point 1 of Episcopal Cemetery Tract Sec. 17

G.L.O. Resurvey notes of 1920

Iron post 3' long 1" diam. with brass cap marked

T142 N R30 W

S17

API

ECR

1920

Angle Point 2 of Episcopal Cemetery Tract Sec. 17

G.L.O. Resurvey notes of 1920

Iron post 3' long 1" diam. with brass cap
marked

T 142 N R 30 W


S 17

AP 2

ECR

1920

Angle Point 3 of Episcopal Cemetery Tract Sec. 17
G.L.B. Resurvey notes of 1920
Iron post 3' long 1" diam. with brass cap marked



Angle Point 4 of Episcopal Cemetery Tract Sec. 17

G.L.O. Resurvey notes of 1920

Iron post 3' long 1" diam. with brass cap marked

T142 N

R30 W

AP4

S17


ECR

1920

Angle Point 5 of Episcopal Cemetery Tract Sec 17

G.L.O. Resurvey notes of 1900

Iron post 3' long 1" diam. with brass cap marked



Angle Point 6 of Episcopal Cemetery Tract Sec. 17

G. L. O. Resurvey notes of 1920

Iron post 3' long 1" diam. with brass cap marked

E C R

AP 6

T142N R36W

S17

1920

Angle Point 7 of Episcopal Cemetery Tract Sec. 13

G.L.O. Resurvey notes of 1920

Iron post 3' long 1" diam. with brass cap marked

ECR
AP 7

T142N

R30W


S17

1920

Angle Point 1 of Catholic Cemetery Tract Sec. 17

G. L. O. Resurvey notes of 1920

Iron post 3' long 1" diam. with brass cap
marked




Angle Point 2 of Catholic Cemetery Tract Sec. 17

G.L.O. Resurvey notes of 1920

Iron post 3' long 1" diam. with brass cap marked

T142N

R306W



S17


1920

Angle Point 3 of Catholic Cemetery Tract Sec. 17

G.H.D. Resurvey notes of 1920

Iron post 3' long 1" diam. with brass cap
marked

TI42N
R30L0




S17

1920

Angle Point H of Catholic Cemetery Tract Sec 17

G. L. C. Resurvey notes of 1920


Iron post 3' long 1" diam. with brass cap
marked



1 of Episcopal Church Tract Sec. 20
Angle Point ~~2 of Catholic Cemetery Tract~~

G.L.O. Resurvey notes of 1920

Iron post 3' long 1" diam. with brass cap
marked



Angle Point 2^d Episcopal Church Tract Sec 17
G.L.O. Resurvey notes of 1920
Iron post 3' long 1" diam. with brass cap
marked

T142N AP2

R30W ECR

S17

1920


Angle Point 3 of Episcopal Church Tract Sec. 77
G. L. O. Resurvey notes of 1920
Iron post 3' long 1" diam. with brass
cap marked

T142N | ECR
R30W | AP3
S17
1920

Angle Point 4 of Church Church Tract Sec. 17

G.L.O. Resurvey notes of 1920

Iron post 3' long 1" diam. with brass cap marked



T142N R30W

1920

Y-3

Center South 1/16 Cor. Sec. 31

G.L.C. Resurvey notes of 1917

Iron post 3" long 1" diam. with brass cap
marked

C
S 1/16 S31

C
1917

N. Pine 7" N74°W 5 1/2 - 3.30'

N. Pine 5" N60°E 5 1/2 - 3.30'

5680-11 by Wittcraft & Emery - 1965

3-12-81 B. Olson Monument OK

2 NEW Bts

18" N. PINE N52°E 59.80 MKD. CS 1/16 S31 BT

9" W. OAK S82°W 49.91 " CS 1/16 S31 BT

LINE to St. N & E

~~1, 2~~ X, Y-3

Angle Point 1 of Allotment 1589 and Angle Point 4 of Allotment 1349 Sec. 31

G.L.C. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

AP 4	
TR	
1349	TR
AP 1	1607
TR	531
1589	
	1917

3-12-81 B. Olson Monument OK

3 NEW Bts

9" ROAK S12°W	22.81'	MKD,	AP1 TR 1589	B+
6" ROAK S80°W	17.40'	"	AP1 TR 1589	B+
12" Birch N49°W	26.40'	"	AP4 TR 1349	B+

X-3

Center Quarter Sec. 31

G.L.C. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap marked

C $\frac{1}{4}$ S 31

1917

R. Oak 7" N 62 $\frac{1}{2}$ ° E 62 IKs - 40.92'

Poplar 6" N 31° W 95 IKs - 62.70'

3-12-81 B. Olson Monument OK

3 NEW Bts

7" OAK S 82° W 14.13' MKD. C $\frac{1}{4}$ S 31 B+

11" OAK N 72° W 12.66' " C $\frac{1}{4}$ S 31 B+

9" OAK N 38° E 3.80' " C $\frac{1}{4}$ S 31 B+

W, X-3

Angle Point 3 of Allotment 1625 and Angle
Point 4 of Allotment 1740 and Angle Point
1 of Allotment 1587 and Angle Point 2 of
Allotment 1607 S31

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

AP4 | AP3

TR | TR

1740 S31 | 1625

AP1 | AP2

TR | TR

1587 | 1607

1917

5680-11 by Wittbroff & Emery - 1965

2-18-81 B. Olson Monument OK

4 NEW Bts } 2693' MKD. AP3 TR 1625 Bt

8" ROAK N44°E } 41.56' " AP2 TR 1607 Bt

8" Birch S77°E } 14.67' " AP1 TR 1587 Bt

10" ROAK S13°W } 28.70' " AP4 TR 1740 Bt

7" ROAK N44°W

74

W-3

Center North 1/16 Cor. Sec. 31

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. With brass cap
marked

N 1/16 | S 31

C

1917

Poplar 6" S13 $\frac{3}{4}$ ° E 77 1/2 - 50.82'W. Oak 4" N34 $\frac{1}{4}$ ° W 60 1/2 - 39.60'

2-18-81 B. Olson Monument OK

3 NEW Bts

7" W. Oak N5°W 1280' MKD, CN 1/16 S31 Bt

10" Birch N56°E 4558' " CN 1/16 S31 Bt

6" W. Oak S26°W 4108' " CN 1/16 S31 Bt

Line to std runs S & E

25

Angle Point 2 of Allotment 1407 and Angle
Point 5 of Allotment 1607 Sec. 31

G.L.O Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

S 31	
AP 5	AP 2
TR	TR
1607	1407
1917	

3-10-81 B. Olson Monument OK

3 NEW B + s

7" W.OAK S75°W 42.47' scribed AP 5 TR 1607 S 31 B +

10" R.OAK N40°E 76.59' " AP 5 31 B +

10" W.OAK S78°E 1989' " AP 2 TR 1407 S 31 B +

Center East 1/16 Cor. Sec. 31

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

E 1/16
C ————— C

S 31

1917

N. Pine 5" N 82 $\frac{3}{4}$ ° E 44 KS - 29.04'

W. Oak 4" S 16° W 36 KS - 23.76'

X-2

Center West 1/16 Cor. Sec. 31

C.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

W 1/16
C ————— C

S 31

1917

R. Oak 4" N60°E 13.1K5 - 8.5E'

R. Oak 12" S62°W 19.4K5 - 128.04'

2-27-81 B. Olson Monument OK

3 new Bts

9" R. OAK N50°W 31.23' MKD. CW 1/16 S31 BT

11" R. OAK N6°E 16.95' " CW 1/16 S31 BT

8" R. OAK N50°E 21.31' " CW 1/16 S31 BT

Y-4

South East 1/16 Cor. Sec. 31

G.L.O. Resurvey notes of 1917

Iron post 3' long 1" diam. with brass cap
marked

SE 1/16 S 31

1917

R. Oak 5" N58°E 187 IK5 - 123.42'

Poplar 16" S87½°W 168 IK5 - 110.88'

5680-11 by Wittkeft & Emery - 1965

3-9-81 B. OLSON MONUMENT LEANS

Slightly to the west

3 NEW Bts

8" OAK S22°E 27.54' MKD SE 1/16 S31 BT

9" OAK N78°W 29.53' " SE 1/16 S31 BT

7" OAK N6°E 18.20' " SE 1/16 S31 BT

9-24-02 R MAIN

FD IRON IN MIXED HARDWOODS 198/BTS

ARE OK. HEAVY 8 FT STEEL SIGN POST

400 FT WEST