

TISON R27W  
CORNER  
RESTORATION  
BOOK #3

WY  
FIELD BOOK  
820071

TISON R27W CORNERS

BOOK 3





① SEE BOOK #1 PAGE 35 FOR RECOVERY INFO.

SECTION CORNER TO SECTIONS 4, 5, 32 & 33

5/11/88 KW-TW-GR-CK & GB

SET COUNTY MONUMENT WITH ALUM. CAP MARKED

FLUSH WITH GROUND TISON

R27W S32/S33

S5/S4

T149N

1988

RLS ~~NO~~ 14677

WITNESSED BY

ASPEN 9 N23W 43.35' NO EVIDENCE

ASPEN 9 N24E 29.42' NO EVIDENCE

ASPEN 10 S30E 7.00' NOWA STP/W/BT

ASPEN 9 S34W 15.90' NOWA STP/W/BT

8' STEEL SIGN POST NORTH 3.0'

DOCUMENT # 400658

FSLP ON 8" N. PINE 417' SOUTH OF SEC. COR. ON WEST SIDE

OF FR # 2229 & 300' NORTH OF ROAD INTO DEMONSTRATION AREA

10-22-2012 R. MAIN

FD IRON IN PLACE AND GAS SURVEY GRADE.

SURROUNDED BY YOUNG ASPEN.

ITASCA CO COORDS N = 194673.387

E = 405137.294

②

(2)

EAST QUARTER CORNER TO SECTION 33

5/17/88 K.W. - T.W. - G.R. - CK - GB

SET COUNTY MONUMENT WITH ALUM. CAP MARKED

FLUSH WITH GROUND

T150 N R 27 W

S33  $\frac{1}{4}$  S34

1988

RLS 14677

WITNESSED BY

ASPEN 6 N75W 42.36'

W. SPRUCE 8 N81E 34.56'

ASPEN 9 S64W 13.24'

8' STEEL SIGN POST WEST 4.0' AND EAST 4.4'

ASPEN 7 S76E 3.6' WITH FSLP

DOCUMENT # 400656

SEE BOOK #2 Pgs. 63 &amp; 78 FOR SEARCH INFO.

(2)

③ SEE BOOK 2 PAGE 67 FOR SEARCH+RECOVERY

EAST MEANDER CORNER ON CODDINGTON LAKE

BETWEEN SECTIONS 2+35

6/20/88 KW-GR-CK

SET F.S. ROD MONUMENT LONG IN SOFT BOG ON

EAST SIDE OF CODDINGTON LAKE WITH ALUM. CAP MKD.

OLD POST SET ALONGSIDE TISON R27W

OF NEW MONUMENT

MC 535

52

T149N

1988

WITNESSED BY

RLS 14677

CEDAR SNAG 12 N71E 70.22' MKD 535 BT

ASH 7 EAST 113.05' MCS2 BT

ASH 11 S70E 120.46' MCS2 BT

DOCUMENT # 400661

(4) SEE PAGE 27 BOOK 2 SEARCH EVIDENCE

CORNER TO SECTIONS 22-23-26+27

6/8/88 KW-TW-GR-GB

SET COUNTY MONUMENT WITH CAP MARKED

FLUSH WITH GROUND

TISON R27W

S22|S23

S27|S26

1988

RLS 14677

WITNESSED BY

BALMIE 8 N88E 26.80' MKD S23 BT DOWN

BALMIE 14 S16E 22.34' " S26 BT DOWN

ASPEN 8 S48W 24.45' " S27 BT DOWN

BALMIE 11 N48W 6.39' S22 BT DOWN

8' STEEL POST NORTH 410'

10-29-07 R MAIN

GPS IRON. ALL 1988 BTS ARE DOWN

CERTIFICATE FILED

(4)

⑤ SEE BOOK 2 PAGE 55 FOR SEARCH INFORMATION  
CORNERS TO SECTIONS 5-6-31-32

5/25/89 GB-CK

MADE ANOTHER SEARCH FOR EVIDENCE OF ORIG. BT'S.

BUT COULDN'T FIND ANY STUMPS IN MUCK IN SWP.

BELIEVE THEY MAY HAVE BURNED AND ROTTED AWAY

WE CHECK ROSE'S LAND TIES AND AGREE WITH DISTANCES

TO NORTH 100' - EAST 48' + WEST 46' - BY USING

LARGE SNAGS AROUND POND AS EDGES - THESE TIES

WOULD FIT VERY GOOD - AS BEAVER HAVE FLOODED AREA

IN YEARS PAST AND KILLED MANY TREES AROUND

EDGES - THE AREA TO LIVE TIMBER HAS NOW CHANGED

ROSE'S TIE TO SOUTH WAS 210' - WE CHECK THIS AND

FIND THAT HE WAS GOING UP SLOPE AT THIS DISTANCE

OUR CALL WOULD BE AT 190' TO TOE OF SLOPE

POND NOW IS ABOUT 18" DEEP MUCK - WITH MANY WINDFALLS

IN MUD - SMALL STREAM FLOWS INTO SWAMP FROM NORTH

AND FLOWS NEXT TO CORNER MONUMENT.

WE USE OLD POST POINT AS POSITION FOR SECTION COR.

AND LAND TIES BY ROSE & ORIG. SURVEY AS BEST

POSSIBLE EVIDENCE OF ORIG. COR.

MANY HOURS WERE SPENT IN CHAINING AND SEARCH

THERE WERE NO GOOD BEARING TREES AVAILABLE IN

AREA AS ONLY ASPEN + DEAD SNAGS REMAIN WITHIN REASONABLE

DISTANCE OF CORNER - AREA TO NE-E - SE IS ASPEN

REGENERATION - FLOODED AREA + WINDFALLS ARE TO SOUTH

AND SOUTHEAST - BEAVER DAM IS TO SE APPROX 500'

CC DONE

⑤

TO PERPETUATE THIS CORNER WE SET

2" X 48" BRASS CAPPED IRON PIPE - SET OVER

8' LONG STEEL SIGN POST 24" ABOVE SWAMP

CAP IS MARKED

T150N R27W

4" SQD X 8' LONG ASH

S31 | S32

POST BESIDE MONU.

S6 | S5

T149N

1989

WITNESSED BY

USFS

ASH 10 N 87W 117.65' MKD S31 BT

8' STEEL SIGN POST SOUTH 6.0' 54-9

8' STEEL SIGN POST S45W 32.9' 54-9

8' STEEL SIGN POST S87E 43.5' 54-9

OLD POST POINT AT SOUTH EDGE OF PIPE

CHAINED S3W 300' AND MKD PICKET - WILL CONTINUE

SOUTH LATER

5/25/89 Curt Krause

RAN LINE AT N12W FROM THIS CORNER TO STATION

SEE BACK PAGE IN BOOK #2 T150N R27W

3000' MKD PICKET - WILL CONTINUE ON FRIDAY 5/26/89



⑥ SEE BOOK 2 PAGE 41

CORNER TO SEC'S. 29-30-31-32

5/25/89 GB-CK

START LINE FROM SEC. COR. 5-6-31-32 - THIS CORNER  
WAS MONUMENTED TODAY

LINE RUN AT N12W TO STATION 3000' N END OF DAY

5/26/89 GB-CK

CONTINUE CHAINING AT N12W TO COMPUTED DISTANCE  
OF 5616' - USED ROSE'S NOTES FOR SECTION 32

OUR LINE FELL AT EAST SIDE OF 21" BASSWOOD  
WHICH HAS BEEN BLAZED ON 4 SIDES

FOUND SMALL NAIL USED BY CCC'S. TO PUT UP TAGS  
ON NORTH SIDE OF TREE - NO TAG COULD BE LOCATED

BELIEVE THEY MISTOOK BASSWOOD FOR 14" ASPEN

WE CHAINED ROSE'S DISTANCE OF 5520' FROM EAST  
SEC. COR. WHICH IS NOW MONUMENTED

AND CHAINED DISTANCE FROM SEC. COR. TO SOUTH  
OF 5616' - BOTH DISTANCES FELL AT EAST EDGE  
OF BLAZED BASSWOOD - BELIEVE THIS IS GOOD COR.

WE MEASURE 7.9' MAG. NORTH FROM BASSWOOD  
AND SET 3" x 3" x 48" DRY BALSAM POST FOR  
TRUE CORNER - PLACE 10" DIA. NEARLY FLAT  
MAGNETIC ROCK (HOT) AT NORTH SIDE OF POST

TIES TO POST

ASH	9	S30E	32.40'	SPK + TAG
MAPLE	8	S50W	31.45'	NAIL & TAG
BASSWOOD	12	N57W	13.70'	SPK + TAG

CC DONE

⑥

CORNER IN HARDWOODS + ASPEN - HARDWOOD  
RIDGE NE + SW IS 125' TO WEST OF POST  
LOW WET AREA BRS. NE + SW - 200' SOUTH OF COR.  
PUT FSLP ON 4" MAPLE ON EAST SIDE OF PR 2229D  
ROAD BRS. NW + SE - SEC. COR. IS N88W 1240'  
LINE FROM EAST WAS RUN AT DUE WEST AND  
SHOULD BE RUN AT N88W

(7)

QUARTER CORNER BET. SEC'S. 3+34

SURVEY RETRACTED IN 1896 BY CHARLES NUTTER

NEW 1/4 CORNER

FOUND 1882 TAM 10 N65W 6.6'

MARKED NEW BT.

TAM 12 S73E 23.1'

12/11/90 GB-CK

RAN LINE AT DUE WEST FROM APPROX. NE COR. OF  
SEC. 3 (IN SPRUCE SWAMP)

650' W LV. SWP. - 1100' W ENT LARGE ASPEN STAND

1900' W ENT ASPEN CUTOVER - 1685' W WOODS TRAIL

NYS - 2410' W WOODS TRAIL NYS - 2480' W ENT SWP.

2640' MKD ON BLAZED CEDAR - SEARCH 1 HR. NO

EVIDENCE WAS FOUND - THERE ARE MANY LARGE TAM &amp;

CEDAR STUMPS AND LOGS LYING IN SWAMP - THIS SWAMP

WAS CUT OFF IN PAST YEARS - TIES INDICATE WE

SHOULD MOVE SOUTH AND WEST FOR THING TO FIT ON

THIS HALF MILE

12/12/90 GB-CK

MOVE APPROX. 1/4 POSITION 50' WEST AND 30' SOUTH  
FROM ABOVE LOCATION AS LAND TIES WOULD FIT VERY

WELL TO EAST NOW - PLACE FSLP ON 13" CEDAR

38' SOUTH OF APPROX. 1/4 COR. SEARCH AREA - THIS

POSITION IS NOW 2640' W OF APPROX. NE COR. OF SEC. 3

SEARCHED 1 1/2 HRS. TODAY - NO EVIDENCE WAS FOUND

(7)

12/19/90 GB-WS

CHAINED FROM APPROX. NW COR. SEC. 3 - 2700' E

TO APPROX. 1/4 ESTABLISHED ON 12/12/90

LINE FROM WEST FELL AT APPROX. 1/4 LOCATION

SEARCH AREA SHOULD BE NEAR TAG OR TO WEST

NEED TO SEARCH IN SUMMER - COME IN ON

WOODS TRAIL FROM R.R. GRADE NEAR SE COR.

OF SEC. 2 - 4 WHEEL ATV. BEST

6-10-91 CK-GB

SEARCHED 3 HRS. AGAIN - NOTHING COULD BE

FOUND - SET 2" X 6' CEDAR PICKET AT APPROX.

1/4 COR - FSLP AT 38' SOUTH ON 13" CEDAR STILL

WITNESS TO CEDAR PICKET

⑧

## QUARTER CORNER BETWEEN SECTIONS 2+35

NOTES OF ORIG. GOV'T. SURVEY 1882

SET WOOD POST

ASPEN 5 S4W 25 LKS. = 16.5'

SPRUCE 10 N4E 6 LKS. =

RESURVEY BY CHARLES NUTTER 1896

Fd. NO EVIDENCE OF COR. OR B.T'S. OF 1882

SET NEW POST AND MKD. NEW B.T'S.

SPRUCE 9 S41E 11.9'

BIRCH 8 N36W 34.3'

⑧

4/4/73 OK-JP

CHAINED DUE EAST FROM APPROX. CORNER AT  
2-3-34-35 - CHAINED 2700' E PLACE FSLP  
ON 5" ELM AS APPROX. CORNER - NO EVIDENCE  
OF ORIG. CORNER OR B.T'S. - FALLS IN ASPEN  
TIMBER - Fd. OLD BLAZED LINE RUNNING NORTH  
AT 2650' OUR CHAIN ALSO BLAZE ASPEN  
WITH YELLOW PAINT ON OUR LINE

12/6/90 GB-RM-MH

CHAINED FROM WEST APPROX. SEC. COR. 2-3-34-35  
RAN LINE AT DUE EAST - 1020' E CROSS SWP.  
ROAD NE-SW - 1250' E LV. SWP. ENT. ASPEN  
TIMBER AT 2700' E Fd. OLD TAG (1973)  
125' SOUTH OF THIS LINE - ELM NOW SNAG<sup>W</sup>/FSLP  
CONT. EAST TO STA. 5280' E - END OF DAY  
AT 1800' E WOODS TRAIL FROM NORTH - RIBBON  
ON 14" ASPEN EAST SIDE OF ROAD MKD. 1800' E  
TO BE USED BY ENG. TO TIE TO APPROX. COR'S.  
NEW ROAD SURVEY 1990 SOUTH FROM THIS POINT

⑨

QUARTER CORNER BETWEEN SECTION 243

NOTES OF ORIG. GOV'T SURVEY 1882

SET WOOD POST

BALSAM 10 N10E 15 LKS. 9.9'

SPRUCE 10 N15W 20 LKS. 13.2'

⑨

4/4/73 CK-JP

CHAINED NORTH FROM ORIG. CORNER FOUND AT  
2-3-10-11 - CHAINED 2640' N AND ESTABLISHAPPROX.  $\frac{1}{4}$  CORNER. - NO ORIG. EVIDENCE WAS  
FOUND - PLACE FSLP ON 16" ELM AS APPROX. $\frac{1}{4}$  COR. - CONTINUE NORTH TO SEC. COR. 2-3-34-35

12/12/90 GB-CK

FD, FSLP ON 16" ELM SNAG ON EAST SIDE OF WOODS  
TRAIL N45 - THIS TRAIL CONTINUES N+NWTO TOWNSHIP LINE BETWEEN N $\frac{1}{4}$  OF SEC. 3 AND  
NE COR. OF SEC. 3 - ONE TRAIL IS ~~1700'~~<sup>1700'</sup> W OFNE COR. OF SEC. 3 AND OTHER IS 240' E OF APPROX.  
N $\frac{1}{4}$  SEC. 3

(10)

QUARTER CORNER BETWEEN SECTIONS 2+11  
 NOTES OF ORIG. GOVT. SURVEY 1882  
 SET WOOD POST

BALSAM 20 N81W 30 LKS. = 19.8'

SPRUCE 18 S10E 58 LKS. = 38.3'

(10)

1973 CK-JP

FROM SEC. COR. 2-3-10-11 WHICH WAS RESTORED FROM  
 ORIG. BT'S - ~~WE~~ WE CHAINED A DISTANCE OF 5340'  
 TO ORIG. COR. EVIDENCE FOUND AT SEC. COR. 1-2-11-12  
 AT STA. 2640'E OR FROM SW COR. OF SEC. 2  
 ESTABLISH APPROX. 1/4 COR 2+11 - PLACED FSLP  
 ON 8" ASPEN AS APPROX. 1/4 COR. - THIS TAG  
 SHOULD BE MOVED 30' EAST TO ~~BE~~ BE MIDPOINT  
 NO ORIG. EVIDENCE WAS FOUND AT THIS TIME  
 CORNER IS IN ASPEN STAND WITH SOME BURNED  
 PINE STUMPS IN AREA - DIDN'T SPENT MUCH  
 TIME SEARCHING AS THERE IS 10" SNOW COVER,  
 AND THINGS ARE FROZEN DOWN  
 TAG WAS SET AS LINE WAS RUN FROM WEST  
 WE DIDN'T GO BACK ACCORDING TO NOTES AND  
 MOVE - MORE SEARCH SHOULD BE DONE  
 IN SUMMER - JOHN PEIRSON NEW OF THIS CORNER  
 POST & SPRUCE BT IN 1940'S - BUT HE REMEMBERS  
 SPRUCE WAS WINDFALL OVER POST - NO TRACE  
 AT THIS TIME COULD BE FOUND

(11)

QUARTER CORNER BETWEEN SECTIONS 4+33

NOTES OF ORIG. GOVT. SURVEY 1882

SET WOOD POST

ASPEN 10 S50E 13 LKS. =

ASPEN 9 N31W 23 LKS. =

(11)

12/19/90 GB-WS

CHAINED FROM CENTER OF CO. ROAD # DUE  
 EAST 2640' - NO SEARCH AS APPROX. CORNER  
 AREA FALLS IN ASPEN REGENERATION AREA  
 NO EVIDENCE REMAINS - NOTHING TO PUT TAG  
 ON, JUST 1" ASPEN - CONTINUE EAST FROM  
 STA 2640'E OR APPROX. 1/4 COR. LOCATION

SECTION CORNER TO SECS. 17-18-19-20

CONTINUED FROM BOOK #1 PAGE 44

9/24/91 CK

BEARING TREES MARKED IN 1974

BIRCH 9 N69W 43.6'

NOW BIRCH SNAG 15' HIGH - SCRIBE VISIBLE

ASPEN 7 N49E 47.1'

NOW ASPEN STUB 20' HIGH - SCRIBE VISIBLE

ASPEN 8 S64E 33.6'

NOW BROKEN OFF 48" HIGH - SCRIBE VISIBLE

BASSWOOD 9 S75W 26.5'

NOW 11" ALIVE - BUT DAMAGED - SCRIBE VISIBLE

MONUMENT AND SIGN POST - IN PLACE

THEY HAVE LOGGED EVERYTHING AROUND

CORNER FOR AT LEAST A 1/4 MILE

EXCEPT SW QUADRANT - AND THAT IS

BEING LOGGED TODAY - AS IT IS STORM

DAMAGED FROM HAIL STORM LAST YEAR

THERE WILL BE NOTHING STANDING

NEAR CORNER WHEN THEY ARE FINISHED

TAG AT ROAD ALSO GONE

PAINTED UP REMAINS AT CORNER

LOGGER SAID THEY WOULD BE CAREFULL

AROUND CORNER - IN 1 WEEK THEY

WOULD BE FINISHED

CORNER IS 265' EAST OF FR # 3355

10/21/91 BRAMA

Placed 8' steel sign <sup>posts</sup> as reference objects:

- |    |           |                |                             |
|----|-----------|----------------|-----------------------------|
| 1. | Sign post | N50° W @ 11.57 | <sup>Survey</sup> Sign att. |
| 2. | Sign post | N46 E @ 11.48  | "                           |
| 3. | Sign post | S29 E @ 11.12  | "                           |
| 4. | Sign post | S37 W @ 11.49  | "                           |

CENTER SOUTH  $\frac{1}{16}$  TO SECTION 18

NOTES BY JOHN J. ROSE 1927

FOLDER 13 Pg. 80

RAN N+ S CENTER LINE OF SEC. 18 - 5472.2'

N  $\frac{1}{2}$  IS 2690.0' AND S  $\frac{1}{2}$  IS 2782.2'FOLDER 13 Pg. 56 TIES TO C  $\frac{1}{4}$  BY ROSEBIRCH 7 S  $31^{\circ}34'E$  27.7'BALSAM 5 S  $50^{\circ}30'W$  2.6'~~RECORDED ON WRONG PAGE~~

6-10-91 CK-6B

WE ESTABLISHED NEW POSITION FOR C  $\frac{5}{16}$   
COR. AS FOLLOWSFROM POSITION AS REESTABLISHED ON  
6-7-91 WE MOVE AT N  $88^{\circ}E$  44'  
AND PLACED ESLP ON 10" J. PINE AS APPROX.  
C  $\frac{5}{16}$  COR. SEC. 18 - TAG IS FACING FR 2227  
75' NORTH OF ROAD NE-SWANOTHER WIND STORM HIT AREA AGAIN IN  
FALL OF 1992 AREA WAS NEARLY LEVELED  
BELIEVE TAG ON 10" J. PINE IS NOW A STUB

12-13-83 GB-JA

CHAINED FROM BRASS CAPPED IRON PIPE AT  $\frac{1}{4}$  COR. BETSELS. 17+18 - RAN LINE AT S  $88^{\circ}W$  AND CHAINED12351.6' - FOUND CE  $\frac{1}{16}$  COR. BY ROSE - LINE ANDDISTANCE FIT ROSE'S. NOTES. CONT. S  $88^{\circ}W$  TO C  $\frac{1}{4}$ JAN. 1984 BART TOBIN CHAINED NORTH FROM  
S  $\frac{1}{4}$  COR. SEC. 18 - WHICH IS BRASS CAPPED IRON PIPE  
IN FLOODED IMPOUNDMENT - ON ICE CHAINED ROSE'S  
DISTANCE 1391.1' AND PLACED TAG ON 8" J. PINE  
S  $73^{\circ}E$  10.0' FROM END OF CHAINED DISTANCE

6-7-91 GB YCK

FROM POSITION CHAINED NORTH FROM S  $\frac{1}{4}$   
WE RAN LINE AT N  $2^{\circ}E$  - AND CHAINED 1391' - OUR  
LINE FELL 46' WEST OF TAG PLACED IN 1983  
OUR LINE SHOULD HAVE BEEN RUN DUE NORTH  
Fd. ASPEN STUB WITH ESLP FROM 1983 - TOP WAS BLOWN  
OFF IN PAST WIND STORM - OUR CHAINED DISTANCE  
FELL 14' NORTH OF 1983 TAG - REMOVED TAG FROM  
1983 AND PLACED NEW TAG ON 12" ASPEN STUB  
8' HIGH - APPROX. C  $\frac{1}{4}$  COR. SEC. 18 WOULD BE 14'  
NORTH OF TAG ON STUB - APPROX. CORNER IS IN  
ASPEN CUTOVER + WINDFALLS ON SIDE SLOPE  
NO TRACE OF ROSE'S. POST OR RT'S COULD BE  
FOUND - REAL BAD STORM DAMAGE IN AREA  
PLUS AREA WAS LOGGED YEAR OR 2 BEFORE  
STORM



CENTER QUARTER TO SECTION 18

SEE PAGE 13 FOR C<sup>1</sup>/<sub>4</sub> + TIES

NO TRACE OF ROSE'S CORNER COULD BE  
FOUND - AREA LOGGED OVER AND WIND STORMS  
HAVE DESTROYED CORNER POSITION

6-7-91

PLACED NEW FSLP ON 12" X 8" HIGH ASPEN  
STUB - TAG ON NORTH SIDE - APPROX. C<sup>1</sup>/<sub>4</sub>  
IS NORTH 14' FROM TAG

REMOVED TAG ON EAST SIDE BY CREW IN  
1983 - N45 CENTER LINE SHOULD BE  
RUN AT DUE NORTH IN FUTURE

SEE PAGE 13 THIS BOOK FOR CORRECTED  
POSITION

ROSE'S TIES ALONG LINE WOULD HAVE FIT  
VERY CLOSE. - IF OUR LINE WOULD HAVE  
BEEN RUN AT DUE NORTH FROM C<sup>5</sup>/<sub>16</sub>  
TO C<sup>1</sup>/<sub>4</sub> - TIES FROM C<sup>1</sup>/<sub>4</sub> NORTH FIT  
REAL GOOD WITH NOTES

(15)

CENTER NORTH 1/16 TO SECTION 18

NOTES BY JOHN J. ROSE - 1927

FOLDER 13 Pg. 80

RAN N+S QUARTER LINE TOTAL DISTANCE 5472.2'

N 1/2 IS 2690.0' + S 1/2 IS 2782.2'

FOLDER 13 Pg. 84

SET 1/16 #2 SET BALSAM POST 3 1/2" X 4"

SOFT MAPLE 7 N24E 28.9'

POPLAR 12 S72W 25.80'

AT EDGE OF MARSH

(15)

12-21-83 CK-JA-GB

CHAINED SOUTH FROM APPROX. N 1/4 SEC. 18

425'S ENT. SWP NW-SE - 730'S LV. SWP. NE-SW

ASCEND ASPEN + BIRCH RIDGE 1257'S SIGN OF

OLD TRAIL ON RIDGE TOP NW-SE - 1345'S

APPROX. CN 1/16 COR. - SEARCH AREA, BUT COULDN'T

FIND ROSE'S TIES - BLAZED 4" ASPEN 4 SIDES

AS APPROX. CN 1/16 COR. - WE NOW HAVE 14" SNOW

DEPTH - 4" BLAZED ASPEN IS 50'E OF END OF

OUR CHAINED DISTANCE - TIES ALONG LINE WOULD

FIT BETTER WITH THIS CHANGE IN POSITION

6-7-91 CK-GB

CHAINED DUE NORTH OF APPROX. C 1/4 SEC. 18

- 1345' ROSE'S DISTANCE - PLACED FSLP ON 8" ASPEN

ON NORTH SIDE - APPROX. CN 1/16 IS 6' NORTH OF TAG

NO TRACE OF ROSE'S POST OR BT'S. COULD BE

FOUND - LOWLAND SWAMP IS SW OF APPROX. COR.

Fd. DEAD ASPEN SNAG BLAZED 4 SIDES AS APPROX.

CN 1/16 IN 1983 - SNAG IS 14' SOUTH OF NEW POSITION

ROSE'S TIES FROM SOUTH FIT OUR LINE AT

TRUE NORTH VERY GOOD - BELIEVE OUR POSITION

FOR APPROX. CN 1/16 SHOULD BE CLOSE TO ROSE'S

POSITION

(16)

CENTER WEST 1/16 TO SECTION 18

NOTES BY JOHN J. ROSE 1927

FOLDER 13 Pg. 78 RANDOM LINE

" " Pg. 88 CORRECTED LINE.

NO CENTER WEST WAS SET BY ROSE  
PLAT SHOWS DISTANCES OF 2505.7

FROM W 1/4 TO C 1/4 SEC. 18

FROM C 1/4 TO CW 1/16 IS 1282.8'

12-13-83 CK-6B

WALK BACK TO APPROX. C 1/4 SEC. 18 AND

RAN LINE S88W - 1283' ROSE'S DISTANCE

TIED RIBBON ON 2" ASPEN AND MARKED APPROX.

CW 1/16 - NOTHING BIG ENOUGH TO PUT TAG ON

AREA HAS BEEN LOGGED OVER - NOW ASPEN

REGENERATION

TIES ALONG LINE

292' W WOODS TRAIL N+S - 410' W ENT. SWAMP

480' W LV. SWP. - 850' W OLD R.R. GRADE

950' W ENT. SWP. - 1200' W LV. SWP.

1230' W OLD LOGGING ROAD

1283' W APPROX. CW 1/16 SEC. 18

CC DONE OK

(16)

(17)

MEANDER CORNER ON EAST  $\frac{1}{16}$  LINE

SOUTH SHORE OF MOOSE LAKE

NOTES BY JOHN J. ROSE 1927

FOLDER 13 Pg. 90

1066.6' NORTH OF CE  $\frac{1}{16}$  - SOUTH SHORE MOOSE LAKESET CEDAR POST 4" X 4" FOR W.C. TO NE  $\frac{1}{16}$ 

SECTION 18

CEDAR 10 S8°15'E 170'

NO OTHER TREES MARKED

CC DONE CK

(17)

9-24-85 CK-GB

FROM CE  $\frac{1}{16}$  SEC. 18 RAN LINE NORTH TO W.C.M.C.  
CHAINED 1053' N TO EDGE OF WATER - CORNER  
WOULD BE 13' NORTH IN MOOSE LAKEFD. 12" CEDAR WINDFALL LYING ON SHORE TO SE  
DISTANCE AND BEARING WOULD FIT TO CORNER  
IN LAKEPLACED FSLP ON ASH 10" S8°W-33.0' FROM  
POSITION OF CORNER IN LAKECORNER IS JUST WEST ALONG SHORE LINE  
FROM MOOSE LAKE PUBLIC ACCESS ON SOUTH  
END OF LAKE

(18)

NORTH  $\frac{1}{16}$  CORNER BETWEEN SECTIONS 17+18

NOTES BY JOHN J. ROUSE 1927

FOLDER 13 Page 87

MARKED BT'S FOR N $\frac{1}{16}$ 

BIRCH 24 N20E 5.4'

MAPLE 4 S25 $^{\circ}$ 30'W 6.3'

874 CCC NOTES BY L.W. JOHNSON 1-30-34

FD. OAK POST SCRIBED

FSLP ON MAPLE 8" N86E 15 LKS.

FD. BIRCH 20 N20E 8 LKS.

MAPLE 3 S31W 10 LKS.

7-6-73 CK

CHAINED NORTH FROM  $\frac{1}{4}$  CORNER BETWEEN  
SECTION 17+18 - 1328' TO APPROX N $\frac{1}{16}$  COR.

FD. OLD FSLP ON 12" MAPLE LYING ON GROUND

FD. TIMBER BOUNDARY SIGN ON 8" MAPLE BLAZED  
20' WEST OF APPROX. COR.

PLACE FSLP ON 3 MAPLE AS APPROX. COR.

DIDN'T HAVE ROSE'S NOTES IN 1973

CC DONE CK

(18)

1244.8' EAST OF ~~6N $\frac{1}{16}$~~ <sup>NE $\frac{1}{16}$</sup>  AND 1338' NORTH OF ~~6E $\frac{1}{16}$~~   
1331' NORTH OF  $\frac{1}{4}$  CORNER (PAGE 87 DRAWING)

S.E. CORNER OF SECTION 23

SEE BOOK 2 Pg. 25 FOR SEARCH + HISTORY

5-12-88 KEN WHITEHORN, TIM WOTZKA

GREGG ROBERTSON ITASCA COUNTY

C. KRAUSE + GARY BRAMA

IN PLACE OF TEMP. STAKE

SET 30" DRIVEABLE ALUM. MONUMENT

WITH CAP MARKED

T150N R27W

S23 S24

S26 S25

1988

RLS 14677

WITNESSED BY

W. SPRUCE 13 S23W 40.50' MKD S26 BT

W. OAK 5 N19W 88.79' " S23 BT

W. OAK 6 N32E 42.95' " BT

W. OAK 4 S29E 59.12' X AT BASE

(20)

QUARTER CORNER BETWEEN SECTIONS 9+16

NOTES OF ORIG. GOV'T. SURVEY 1882

SET WOOD POST

J. PINE 12 N53W 4 LKS. 2.64'

J. PINE 15 S63E 25 LKS. 16.50'

NOTES BY JOHN J. ROSE 12-30-31-29

FOLDER 14 Pg. 55

2673.35' FROM SEC. COR. SW OF SEC. 9

FELL 6.3 NORTH OF 1/4 COR.

TIES ALONG LINE BY ROSE

975' HUB - 1500 LV. SWP NYS ENT. HIGHLAND

1629.1 HUB - 2673.35' 1/4 COR.

874 CCC NOTES BY L.W. JOHNSON 1-31-34

Fd. POST 3"x3"x30" SCRIBED

FSLP ON STUB 10 S58E 40 LKS. = 26.4'

EAST RANDOM

33 CHS. LV. TAM. SWP. NE-SW 67" CREEK 30 LKS. FLOW SE (20)

40" TEMP 1/4

55 CHS. ENT SWP.

80.26. SEC COR.

40.13 1/4 COR.

TIM WATKA

ITASCA COUNTY

TOLD ME ON 4/29/97

THEY HAVE MONUMENTED

THIS CORNER

(21)

EAST 1/16 BETWEEN SECTIONS 9+16

NOTES BY JOHN J. ROSE 12-31-26

FOLDER 14 Pg. 58

DISTANCE FROM S 1/4 SEC. 9 TO SE COR. 2672.6'

1336.3' SET E 1/16 AT PROPORTIONAL DISTANCE.

SET POST

MKD BT'S.

SPRUCE 5 S42E 12.2'

SPRUCE 4 N69W 6.3'

874 CCC NOTES BY L.W. JOHNSON 1-31-34

Fd. POST 4" x 4" x 30" HIGH SCRIBED

ESLP ON TAM. STP. 10" SSIE 43 LKS. = 28.38'

CORNER IN SPRUCE + TAM. SWAMP

HIGHLAND 2<sup>132'</sup> CHS. NORTH - MOOSE CREEK 4<sup>264'</sup> CHS. TO EAST



## QUARTER CORNER BET. SEC'S. 34 &amp; 35

N. 0°10' E., bet. secs. 34 and 35.

- .50 Present day shoreline of Coddington Lake, bears S. 36° E. and N. 36° W.
- 23.00 U.S. Forest Service Road 227, bears N. and S. 60° W.
- 28.975 The 1/4 sec. cor. of secs. 34 and 35, perpetuated on a plat entitled "Grattan Look-Out Site" prepared by J. A. Gjelhaug in 1936, determined at a post hole in the ground; from which the remains of the orig. bearing trees:

A severely decayed pine stump, bears N. 22° E., 26 lks. dist. (Record: 28 lks. dist.)

A stump hole, with remains of pine fragments, bears N. 52° W., 14 lks. dist. (Record: N. 33° W., 15 lks. dist.)

and the remains of a 1936 bearing tree:

A pine stump, bears N. 23 1/2° E., 97.4 lks. dist., with a portion of the decayed tree lying alongside, with a rusty location sign attached.

At the cor. point

Set an aluminum post, 30 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, over a "DEEP-1", with aluminum cap mkd.

T150W R27W  
1/4  
S34|S35  
1990

from which the 1960 bearing trees:

A Norway pine, 19 ins. diam., bears S. 37° E., 49.1 lks. dist., mkd. with heated blaze.

A white pine, 9 ins. diam., bears S. 11° E., 19.7 lks. dist., mkd. with heated blaze.

and a new bearing tree:

A white spruce, 8 ins. diam., bears N. 25° W., 50 lks. dist., mkd. 1/4 S34 ST.

From this cor., the 1/4 sec. cor. of secs. 34 and 35, erroneously reestablished in the 1960 dependent resurvey, bears N. 58° E., 17 lks. dist., set, mkd. and witnessed as described in the official record. This monument was removed.



Corrective Resurvey of the Adjusted Meander Line, Sec. 34,  
T. 150 N., R. 27 W., 5th P.M., Minnesota

(Restoring the meander line as recorded  
by J. R. King, in 1882)

From the meander cor. of secs. 34 and 35 on the NE shore  
of Coddington Lake.

Thence, with the adjusted meander of sec. 34.

N. 63°38' W., over Coddington Lake.

4.689 Adjusted position for angle point no. 1, falls in  
Coddington Lake.

N. 41°56'30" W.

9.458 Adjusted position for angle point no. 2, falls in  
Coddington Lake.

N. 5°55'30" W.

.736 North shore of Coddington Lake; point selected for a  
witness point.

Set a copper-coated steel rod, 30 ins. long, 9/16 in.  
diam., 28 ins. in the ground, with a 1 1/2 in. diam.  
bronze cap mkd.

CHAINS

T150N R27W  
WP|S34  
BLM  
1990

from which the 1960 bearing trees:

66.0' A Norway pine, 11 ins. diam., bears N. 70° W.,  
100 lks. dist., mkd. with a healed blaze.

25.54' A white spruce, 14 ins. diam., bears N. 48° W.,  
38.7 lks. dist., mkd. with a healed blaze.

From this point, the point for the special meander cor.  
erroneously established in the 1960 survey, bears  
N. 83°16' W., 44.3 lks. dist., set, mkd. and witnessed as  
described in the official record. This monument was  
removed.

592.284'

9.710 Adjusted position for angle point no. 3.

Set an aluminum post, 30 ins. long, 2 1/2 ins. diam.,  
26 ins. in the ground, over a "DEEP-1", with aluminum cap  
mkd.

T150N R27W

AP3 S34

1990

from which

A Norway pine, 19 ins. diam., bears S. 33° W.,  
41.8 lks. dist., mkd. X AP3 S34 BT.

A birch, 11 ins. diam., bears S. 72° W., 38.8 lks.  
dist., mkd. X AP3 S34 BT.

From this point, angle point no. 3 erroneously established  
in the 1960 survey, bears N. 43°12' W., 1.206 chs. dist.,  
set, mkd. and witnessed as described in the official  
record. This monument was removed and the 1960 NE bearing  
tree was defaced, the SW bearing tree was not, due to  
being healed over.

N. 40°53'30" W.

7.097 Adjusted position for angle point no. 4.

468.402'

6-12-03 R MAIN

8 FT STEEL SIGN POSTS S6°E 3015 FT

6 FT STEEL SIGN POST N41W 1045 FT

DIST TO E OF POST

## CHAINS

Set an aluminum post, 30 ins. long, 2 1/2 ins. diam.,  
26 ins. in the ground, over a "DEEP-1", with aluminum cap  
mkd.

T150N R27W

AP4 S34

1990

from which the 1960 bearing trees:

95.04'

A Norway pine, 15 ins. diam., bears N. 60° W.,  
144 lks. dist., mkd. with scribing visible on  
partially healed blaze. Remarked tree on side  
facing eor. X AP4 S34 BT.

127.38'

A Norway pine, 17 ins. diam., bears N. 35 1/2° W.,  
193 lks. dist., with scribe mks. visible on  
partially healed blaze.

From this point, angle point no. 4 erroneously established  
in the 1960 survey, bears N. 42°43' W., 1.567 chs. dist.,  
set, mkd. and witnessed as described in the official  
record. This monument was removed.

6-12-03 R MAIN

8FT STEEL SIGN POSTS S41E 30FT, N15W 307FT  
DIST TO E OF POST

635.844'

N. 14°42'30" W.

9.634 Adjusted position for angle point no. 5.

Set an aluminum post, 30 ins. long, 2 1/2 ins. diam.,  
26 ins. in the ground, over a "DEEP-1", with aluminum cap  
mkd.

T150N R27W

AP5 | S34

1990

from which a 1960 bearing tree:

164.34 A Norway pine, 25 ins. diam., bears N. 47° W.,  
249 lks. dist., mkd. with visible scribing on  
partially healed blaze.

and a new bearing tree:

CHAINS

21.12'

A spruce, 14 ins. diam., bears S. 83° W., 32 lks.  
dist., mkd. X AP5 S34 BT.

From this point, angle point no. 5 erroneously established  
in the 1960 survey, bears N. 42°28' W., 2.037 chs. dist.,  
set, mkd. and witnessed as described in the official  
record. This monument was removed and the other 1960  
bearing tree was defaced.

N. 50°25' W.

6-12-03 R MAIN

8 FT STEEL SIGN POSTS S15°E 3.2 FT, NSOW 3.5 FT  
DIST TO E OF POST.

715.440'

10.84 Adjusted position for angle point no. 6.

Set an aluminum post, 30 ins. long, 2 1/2 ins. diam.,  
26 ins. in the ground, over a "DEEP-1", with aluminum cap  
mkd.

T150N R27W  
S34

AP6  
1990

from which

28.57'

A poplar, 8 ins. diam., bears S. 35° W., 43.3 lks.  
dist., mkd. X AP6 S34 BT.

11.55'

A white spruce, 8 ins. diam., bears N. 78° W.,  
17.5 lks. dist., mkd. X AP6 S34 BT.

From this point, angle point no. 6, erroneously  
established in the 1960 survey, bears N. 41°52' W.,  
2.584 chs. dist., set, mkd. and witnessed as described in  
the official record. This monument was removed and the  
remaining 1960 bearing tree was defaced.

6-12-03 R.M.A.F.N

8 FT STEEL SIGN POSTS 550°E 3.25 FT, N75°W 3.20 FT  
DIST TO E OF POST

930.732'

N. 75°24' W.

14.102 Adjusted position for angle point no. 7.

Set an aluminum post, 30 ins. long, 5/8 in. diam., 26 ins. in the ground, over a "DEEP-1", with aluminum cap mkd.

T150N R27W  
S34

AP7  
1990

## CHAINS

from which

5.34'

A poplar, 12 ins. diam., bears N. 61° E.,  
0.1 lks. dist., mkd. X AP7 S34 BT.

19.16'

A poplar, 10 ins. diam., bears S. 55 1/2° W.,  
26 lks. dist., mkd. X AP7 S34 BT.

From this point, angle point no. 7 erroneously established in the 1960 survey, bears N. 65°45' W., 2.40 chs. dist., set, mkd. and witnessed as described in the official record. This monument was removed and the 1960 bearing trees are dead.

6-12-03 R. MAIN

8 FT STEEL SIGN POSTS S75°E 3.2 FT, S72°W 3.85 FT

DIST TO E OF POST



534.402

S.  $72^{\circ}51'30''$  W.

8.097 Adjusted position for angle point no. 8.

Set an aluminum post, 30 ins. long, 2 1/2 ins. diam.,  
26 ins. in the ground, over a "DEEP-1", with aluminum cap  
mkd.

T150N R27W

S34

AP8

1990

from which

14.52'

An aspen, 12 ins. diam., bears S.  $18^{\circ}$  E., 22 lks.  
dist., mkd. X AP8 S34 BT.

8.25'

An aspen, 8 ins. diam., bears N.  $42^{\circ}$  W., 12.5 lks.  
dist., mkd. X AP8 S34 BT.

From this point, angle point no. 8 erroneously established  
in the 1960 survey, bears N.  $62^{\circ}04'$  W., 2.78 chs. dist.,  
set, mkd. and witnessed as described in the official  
record. This monument was removed and the 1960 NW bearing  
tree was defaced, the SE bearing tree was not, due to  
being healed over.

6-12-03 R. MAIN

8 FT STEEL SIGN POSTS N  $72^{\circ}$  E 2.085 FT S 27 W 2.055 FTDIST TO  $\frac{1}{2}$  OF POST

655,182

S. 26°33'30" W.

9.927 Adjusted position for angle point no. 9, falls in Dishpan Lake, where it is impracticable to establish a permanent monument.

## CHAINS

From this point, angle point no. 9 erroneously established in the 1960 survey, bears N. 59°05' W., 3.235 chs. dist., set, mkd. and witnessed as described in the official record. This monument was removed and the mks. on the 1960 bearing trees, being healed over, were not defaced.

150,018' S. 0°42' E.

2.273 Point selected for witness cor. for angle point no. 9.

Set an aluminum post, 30 ins. long, 2 1/2 ins. diam., 26 ins. in the ground, with a "DEEP-1" deposited at the base, with aluminum cap mkd.

WC  
T150N R27W

S34 AP9

1990

from which

24.88'

An ash, 12 ins. diam., bears S. 76° W., 37.7 lks. dist., mkd. X at breast height and BT at base.

66.66'

An ash, 10 ins. diam., bears N. 42° W., 101 lks. dist., mkd. X at breast height and BT at base.

1265.022'

21.44 Adjusted position for angle point no. 10.

Set an aluminum post, 30 ins. long, 2 1/2 ins. diam.,  
26 ins. in the ground, over a "DEEP-1", with aluminum cap  
mkd.

T150N R27W

S34 AP10

1990


from which

161.50'

An ash, 15 ins. diam., bears N. 19° E., 25 lks.  
dist., mkd. X AP10 S34 BT.

40.12'

An ash, 10 ins. diam., bears N. 63° E., 60.8 lks.  
dist., mkd. X AP10 S34 BT.



S 43° 02' 16" E

CHAINS

From this point, angle point no. 10 erroneously  
established in the 1960 survey, bears N. 54°57' W.,  
4.236 chs. dist., set, mkd. and witnessed as described in  
the official record. This monument was removed and the  
mks. on the 1960 bearing trees, being healed over, were  
not defaced.

1043.394'

15.809

S 43° 02' 16" E

Adjusted position for angle point no. 11.

Set an aluminum post, 30 ins. long, 2 1/2 ins. diam.,  
26 ins. in the ground, over a "DEEP-1", with aluminum cap  
mkd.

T150N R27W

AP11

S34

1990

from which

11.22'

An ash, 9 ins. diam, bears N. 85° E., 17 lks. dist.,  
mkd. X AP11 S34 BT.

25.74'

An ash, 11 ins. diam., bears N. 46° W., 39 lks.  
dist., mkd. X AP11 S34 BT.

From this point, angle point no. 11, erroneously  
established in the 1960 survey, bears N. 53° 17' W.,  
4.942 chs. dist., set, mkd. and witnessed as described in  
the official record. This monument was removed and the  
mks. on the 1960 bearing trees, being healed over, were  
not defaced.

328.02

S. 72°45'30" E.

4.97 West shore of Coddington Lake, point selected for a witness point.

Set an aluminum post, 30 ins. long, 2 1/2 ins. diam., over an 8 ft. steel sign post, driven into the muskeg bog, with aluminum cap mkd.

T150N R27W

WP

S34

1990

No bearing trees available within limits.

From this point, the special meander cor. erroneously established in the 1960 survey, bears N. 26°37' W., 2.89 chs. dist., set, mkd. and witnessed as described in the official record. This monument was removed and the mks. on the 1960 bearing trees, being healed over, were not defaced.

Thence, over Coddington Lake.

13.251 Adjusted position for angle point no. 13, falls in Coddington Lake.

S. 34°26'30" E.

3.211 South shore of Coddington Lake.

6.295 Adjusted position for angle point no. 14, falls in muskeg. Not monumented.

## WEST QUARTER SECTION 6

NOV 1882 OREG GOUT SURVEY

SET POST 5' X 4"

CEDAR 10 N83E 81ks

BIRCH 14 S83W 61ks

11-20-07 R MAIN

Fd COUNTY IRON IN PRIVATE YARD  
FLUSH TO THE GROUND AND NEAR THE SHORE  
OF MOOSE LAKE. GPS IRON.

END OF  
BOOK