

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


NORTHEAST SIXTEENTH Corner of Section 17, Township 142, Range 27 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 8/23/79 found a GLO brass cap monument bent to the South in
north-south road.
- left monument as found, lowered monument, removed monument (explain)
- On 8/23/79 placed a 2" x 24" galvanized iron pipe with a 3" marked
brass cap.

SKETCH OF REFERENCE TIES



MONUMENT MARKED:

T142N R27W

NE 1/16 S 27

1979

RLS No. 12261

BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page.

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Nancy H. Stevenson
SIGNATURE

9-13-82
DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

264920
OFFICE OF THE COUNTY RECORDER
County of Cass

I hereby certify that this document was filed in the Co. Recorders office at 9:05 A.M. on the 14 day of Sept. A.D., 1982

County Recorder Beulah Hendrich
By MS, Deputy

DOCUMENT NO. 264920

Statement of Evidence:

- 1919 U.S. General Land Office dependent resurvey established this corner and an iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 10" W. Pine S. 40 E 160 links and 4" Poplar N 11 E 83 links.
- 1979 U.S. Forest Service technician C. Krause found the corner monumented with a GLO brass cap monument with top 10" bent to the south. Base was firmly in place. Corner was found in north-south road. The following bearing trees were found: 24" W. Pine S. 40 E 105.6' with overgrown blaze scar facing corner. No evidence was found of the Poplar as this position now falls in road ditch. Two new bearing trees were marked and are shown on this certificate. The bent monument was replaced with a 2" x 24" galvanized iron pipe with a 3" marked brass cap down 12" below road surface.
- 1982 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1982 On Sept. 10 I visited the corner and found items as per the 1979 USFS reports. I accepted the monument as marking the same position as when set in 1919 by the GLO resurvey.