CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 23 , Township 144 N. , Range 25 W. , 5th P.M.	
STATE OF MINNESOTA, County of Cass	
At the corner location shown on the sketch:	
□ On found a	
☐ left monument as found, ☐ lowered monument, ☐ removed monument (explain)	
On 1-24-1985 placed a 5/8" by 5 feet long Aluminum Rod with 3" Aluminum Cap stamped as shown, up 0.70 feet.	
	FERENCE TIES SCALE
A	
5"Tamarack (Top is Dead)	5" Tamarack
	The state of the s
A. RA	8/4·
7,7000	\$7.6. \$7.5.
The state of the s	
T144N R25W	
51	4 513
523 524	
1985 RLS 9235	
2	73000
	-8 ft. Steel Post with
0000	54-9 Sign attached
NOTE: Trees are Blazed and Scribed with B.T. Tags. Distances	NO LIVE TREES
shown are to a 20d Nail in	
Notch painted red on side of Tree.	
`- 3" Tamarack	
Statement of evidence relative to this corner location is on back of page.	
I hereby certify that this document and the data	OFFICE OF THE COUNTY RECORDER
contained herein was prepared by me or under	County of
my direct supervision.	I hereby certify that this document was filed in the Co. Recorders office at 2:05 A .M. on the
James H. Loukes 3/29/85 DATE	15 day of May A.D., 19 85
Registration No. 9235	County Recorder Charling Kaylon
Land Surveyor, CX Professional Engineer	By M S Deputy
☐ County Surveyor, ☐ County Engineer	DOCUMENT NO. 281946

Statement of Evidence:

N21

This corner was originally established in April, 1876, by B.C. Baldwin, Deputy Surveyor. The field notes of that survey are filed in the office of the Secretary of State, St. Paul, Minnesota. Mr. Baldwin's notes state that a post was set to mark the corner and referenced by the following:

- A 5" Tamarack that bears N19°E a distance of 13 links [8.54 feet]
- A 5" Tamarack that bears S2°E a distance of 22 links [14.54 feet]
- A 5" Tamarack that bears S64°W a distance of 13 links [8.54 feet]
- A 5" Tamarack that bears N55°W a distance of 13 links [8.54 feet]

In 1900, A Map of survey by the Corps of Engineers shows that they found the corner.

On August 31, 1984, personnel from Advance Surveying & Engineering Co. made a thorough search for this corner and the above mentioned references but to no avail. This area is all Tamarack swamp, with trees approximately 2" to 3" diameter.

On January 24, 1985, an additional search was made by Advance prior to reestablishing this corner by Obliterated methods by using coordinate position determined from Corps of Engineers Survey done in 1900.