| OF GOVERNMENT CORNER |
|---|
| ,Township <u>143 N •</u> , Range <u>28 W • , 5 th</u> P.M. |
| |
| |
| |
| d monument, removed monument (explain) |
| enter of old road |
| FERENCE TIES |
| 8" Spruce N 58 E 30.83 |
| Tamarack & Spruce bog |
| 8" Spruce S 85 E 27.71' |
| |
| '7" Spruce S 50 E 38.87' |
| de of trees, trees are double blazed 4-3 bearing tree tags attached. |
| ation is on back of page. 291483 |
| OFFICE OF THE REGISTER OF DEEDS County of |
| |

Statement of Evidence: Southeast Corner Section 24, T. 143 N., R. 28 W., 5th P.M.

- U.S. General Land Office survey set a wood post for this corner and marked the following bearings: 6" Tam N 70 E 22 lks., 3" Tam N 20 E 29 lks., 4" Tam N 75 W 33 lks., 7" Tam S 30 W 56 lks.,
- 1920 County Survey Record Book "C", page 340, shows a survey by J.H. Flynn. He found the corner.
- 1920 County Survey Record Book "C", page 393, shows a survey by Ben Clark. He found the corner and set a 3"x24" I.P. with cap.
- 1920 County Resurvey Plat "E-7", by E.B. Horst, shows corner inplace.
- On July 29, Walt Curo set a 2x60" galv. I.P. with brass cap by extending the south line of Section 19-143-27 west by prorating the distance form the South \(\frac{1}{4} \) corner and the West 1/16 corner according to 1920 measurements. Corner is 18" above ground, 6' West of center of road.