

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER


MEANDER NO. 5 Corner of Section 26&35, Township 144, Range 30, 5th P.M.

STATE OF MINNESOTA, County of CASS

At the corner location shown on the sketch:

- On 12-28-87 found a GLO brass cap monument
DATE
- left monument as found, lowered monument, removed monument (explain)
- On _____ placed a _____
DATE

SKETCH OF REFERENCE TIES



BEARINGS ARE APPROXIMATE

Statement of evidence relative to this corner location is on back of page. 303287

I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision.

Ray H. Stearn 3/1/88
SIGNATURE DATE

Registration No. 12684

- Land Surveyor, Professional Engineer
- County Surveyor, County Engineer

OFFICE OF THE REGISTER OF DEEDS
County of Cass

I hereby certify that this document was filed in the Reg. of Deeds office at 9:45 A.M. on the 22 day of March A.D., 1988

Register of Deeds Clondine Kaylor
By MS Deputy

DOCUMENT NO. 303287

Statement of Evidence:

- 1875 U.S. General Land Office survey set wood post for this corner and marked the following bearing trees: 6" Birch S 30 W 6 links and 4" Birch N 60 W 2 links.
- 1930 U.S. General Land Office dependent resurvey reestablished this corner based on a line of blazed trees running west and the 1900 U.S. Engineers drainage map. An iron pipe with a marked brass cap was set to mark the corner. The following bearing trees were marked: 12" Ash N 24½ W 71 links and 6" Elm S 74 W 63 links.
- 1987 County Surveyor's Records in the Recorder's Office were checked and no resurvey information was found on this corner.
- 1987 U.S. Forest Service office in Cass Lake was contacted for information and no resurvey information was found on this corner.
- 1987 Found GLO brass cap monument in good condition and evidence of 1930 bearing trees: 10" Dead Elm S 70 W 41.6' and rotten stump N 24 W 46.1'. Ran line west to West 1/16th corner and northwest corner of Sec. 35. Distances and line compared very well with 1930 survey. Took ties as shown on this certificate.