CERTIFICATE OF LOCATION OF GOVERNMENT CORNER	
Northeast Corner of Section 1 ,Township 142N ,Range 27W , 5th P.M.	
STATE OF MINNESOTA, County of <u>Cass</u>	
At the corner location shown on the sketch:	
On 8-15-90 found a 2"x56" brass capped monument leaning over, so reset from 1985 USFS information, Book #3. □ left monument as found, □ lowered monument, □ removed monument (explain)	
□ Onplaced a	
Monument marked SKETCH OF REFERENCE TIES	
Not to scale R27w R26W	
-N- S36 S31	
S1 S6 Sec. 36	Sec. 31
T142N	
1968 10 inch White Oak	3.2 feet North Sign post
N 83° W 67.80 feet	5 inch White Oak
(1968) N 64° E 122.94 feet (1968)	
Sign post Sign post 8.0 feet East	
3.3 feet	
West ﴿وَيَ أَ 12 inch Aspen من	6 inch Aspen
S 12° W 2.0	gn post S 83° E 140.70 feet
89.00 feet South	
· · · · · · · · · · · · · · · · · · ·	
Sec. 1	Sec. 6
	All trees scribed, painted with a 30d spike, and USFS 54-3 tag.
Statement of evidence relative to this corner location is on back of page. 32,5/63	
I hereby certify that this survey, plan or	OFFICE OF THE COUNTY RECORDER
report was prepared by me or under my	County of
direct supervision and that I am a duly	I hereby certify that this document was filed in
Registered Land Surveyor under the laws of the State of Minnesota.	the Co. Recorders office at 4:17 P. M. on the 21 day of March A.D., 19 90
•	County Recorder Clearles . Kaylar
William C. Clarper	By My Deputy
Date <u>11/12/90</u> Registration No. <u>17767</u>	DOCUMENT NO. 32 5-16 3

```
A25 <u>Striemens of Evidence:</u>section 36
     Cor.1,6,31 and 36 (SE Cor. Sec. 36)
          U.S. General Land Office survey set wood post for
1B72
          corner and the following references were noted:
                    10" S 46 degrees E, 26 Links (17.16 feet)
                    12" N 85 degrees E, 5 Links (3.30 feet) 6" N 59 degrees W, 8 Links (5.28 feet)
          Tamarack
          Cedar
                    10" S 63 degrees W, 29 Links (19.14 feet)
          Spruce
          J.A. Gjelhaug, USFS, found original witnesses:
1937
          Tamarack 12" N 85 degrees E, 5 Links (stump)
                     6" N 59 degrees W, 8 Links (fallen)
          set cedar post and added the following witnesses:
          Balm of Gilead 9" S 59 degrees E, 236 Links (155.76)
1963
          Bob McDonald, USFS, found cedar post (1937) and following:
          Tamarack 12" N 85 degrees E, 3.30 feet (stump)
                     6" N 59 degrees W, 5.28 feet (fallen)
          Cedar
          Balm of Gilead 9" S 59 degrees E, 155.76 feet (stump)
          He set a 2" X 60" iron pipe with brass cap and the
          following references:
                   6" S 49 degrees W, 9.1 feet
          Aspen
                   7" N 64 degrees W, 11.2 feet
          Aspen
                   6" N 18 degrees E, 20.0 feet
          Aspen
                   4" S 68 degrees E, 24.0 feet
          Cedar post 4"x4" with sign attached, West 2.2 feet An
          affidavit as to location of Government corner was filed for
          record in the Cass County Recorders Office from the above
          information by William H. Okerman, RLS, on October 20,1964.
1976
          BLM Dependent Survey recovered a 2" diameter iron pipe
          with brass cap and witnesses:
                   6" N 16 degrees E, 31 Links (20.46 feet)
          Aspen
                   5" S 68 degrees E, 36 Links (23.76 feet)
          Ash
                   6" S 48 degrees W, 14 Links ( 9.24 feet)
          Aspen
                   7" N 62 degrees W, 17 Links (11.22 feet)
          Aspen
8-12-1981 U.S.F.S., recovered a 2" diameter iron pipe with brass
          cap and add new witnesses as follow:
                  12" N 36 degrees W, 23.45 feet
          Aspen
                  8" N 37 degrees E, 30.06 feet
          Aspen
                  12" S 23 degrees W, 12.60 feet
          Aspen
                   4" S 58 degrees E, 59.10 feet
          Eìm
7-24-1982 K. Matson and G. Kosinko, U.S.F.S., recovered a 2"
          diameter iron pipe with brass cap and 1981 witnesses in
          good condition, notes Aspen stump and two Aspen snags.
12-4-1989 Personnel from Kovanen & Osufsen Inc. found USFS monument in
          good condition and added spike to following witnesses:
                  12" N 36 degrees W, 23.45 feet
                   8" N 37 degrees E, 30.06 feet
          Aspen
                  12" S 23 degrees W, 12.60 feet
          Aspen
                  4" S 58 degrees E, 59.10 feet
          Set 8' steel sign post with sign attached, North 5.1 feet
          Set 8' steel sign post with sign attached, West 4.3 feet
This position is traceable to the original GLO corner.
```