CERTIFICATE OF LOCATION OF GOVERNMENT CORNER EAST QUARTER	
SKETCH OF REFERENCE TIES	
WOODS ① SET DNR RP UP 1' SW SIDE 14" OAK ② SET DNR RP UP 2' SE SIDE 12" OAK ③ SET DNR RP UP 3' NE SIDE 14" OAK ④ SE CORNER YMCA CABIN (FARTHEST EAST CABIN)	305. 0 8 0 8 0 8 0 8 0 8 0 9 0 8 0 9 0 9 0 9 0 9 0 9 0 9 0 9 0 9
1983 CASS COUNTY NORTH COORDINATE SYSTEM 1996 ADJUSTMENT N = 155616.62 E = 505648.58	AZIMUTHS ARE OBSERVED WITH A COMPASS
Statement of evidence relative to this corner loc	cation is on back of page. 11/9/00 FOM01869
I hereby certify that this document and the data contained herein was prepared by me or under my direct supervision. SIGNATURE License Number 16098 Land Surveyor, Professional Engineer County Surveyor, County Engineer	OFFICE OF THE COUNTY RECORDER #430974 County of

East Quarter Corner Section 10, Township 140 North, Range 28 West

The Department of Natural Resources, Bureau of Engineering contacted the following offices for information regarding this corner:

MN Secretary of State
Cass County Surveyor
Widseth, Smith and Nolting of Brainerd
Landecker and Associates of Pequot Lakes
Landecker and Associates of Walker
Central Minnesota Surveying
AMI Surveyors and Mappers

1870 The US General Land Office field notes, on file in the Secretary of State's Office, show this corner to be marked with a post and the following bearing trees were marked:

Poplar 6" S10° E 75 links (49.5') Birch 12" S 15° W 10 links (6.6')

1919 Ben Clark found a 3" x 36" Oak post and the Govt. B.T: 12" W. Birch S15W 10 links. He set a 2" x 48" iron monument and took the following ties:

Maple 8" N 22°W 16.7' Oak 4" S 25°E 15.6'

- 1941 Civilian Conservation Corp. set approximate quarter corner 2640' from the south.
- 2000 In March, the DNR survey crew searched and found a 2" x 21" iron pipe laying down with the scribing of "1/4 S" on the side. The bottom portion of the pipe was found 10' away in the ground and in good condition. This pipe is identical to the other Clark iron pipes that we found in the area. A 3/4" x 24" iron rebar was set inside the pipe and flush with the ground. The iron pipe was accepted as marking the original government corner.

Northeast Corner Section 10 - N 01°05'09"E 2647.06' East Quarter Corner Section 11 - N 89°57'24"E 5037.92'

For more information on our survey in this area please contact MN DNR, Bureau of Engineering, Survey Section, 1601 Minnesota Drive, Brainerd, MN 56401