


CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.



Date: 4/28/03 License No: 21367

OFFICE OF THE COUNTY RECORDER
County of CASS

I hereby certify that this document was filed in the Office of the County Recorder at 9:35 o'clock A.M. on the 1st day of May, 2003 A.D.

County Recorder Kathryn M Morby

By: Della Cadwell, Deputy
DOCUMENT NO. 465876

NORTH QUARTER Corner of Section 10, Township 139, Range 30, 5TH P.M.

On 9/25/02 found a 2" IRON PIPE 7" BELOW GROUND

left monument as found, lowered monument, removed monument (explain)


On _____ placed a _____

decl: 5° EAST (ASSUMED)

SKETCH OF REFERENCE TIES

INDEX NO. E-15

Not to Scale



ALL DISTANCES ARE HORIZONTAL
TO NAIL IN BASE OF BEARING TREE.

Statement of evidence for this corner position is on the back of this page

STATEMENT OF EVIDENCE

Index No. E - 15

North Quarter Corner, Section 10, Township 139 North,
Range 30 West, Cass County, Minnesota

- 1865 Wright & Walker, U. S. Deputy Surveyors, originally established this corner point while surveying the interior subdivision lines of Township 139 North, Range 30 West. They set a wood post for the corner position with the following witnesses: A 14 inch White Pine, South 59 ½ degrees East, 25 links; A 7 inch Norway Pine, North 41 degrees East, 45 links.
- 1954 Harold Curo, RLS #3417, shows the true quarter corner on the plat of GILLESPIE'S SUBDIVISION, Document #147795, recorded in Recorders Office ...
- 1965 R. F. Schneider, RLS #5740, found an iron marker in place. He accepted the found iron for the corner position. In survey for Minnesota Department of Natural Resources.
- 2002 September 25, a Landecker & Associates, Inc. survey crew found a 2 inch iron pipe 7 inches below ground. Based on the 1954 Harold Curo plat and the 1965 R. F. Schneider surveys based off the inplace iron. Landecker & Associates, Inc. accepts the found iron for the quarter corner position.