

CERTIFICATE OF LOCATION OF GOVERNMENT CORNER

North Quarter Corner of Section 29
Township 139 N , Range 26 W , 5th P.M.
STATE OF MINNESOTA, COUNTY OF Cass



A000596810

OFFICE OF THE COUNTY RECORDER
CASS COUNTY, MINNESOTA
CERTIFIED, FILED, AND/OR
RECORDED ON

9/26/2013 2:31:00 PM

AS DOC #: A000596810

PAGES: 2

REC FEES: 0.00

KATHRYN M. NORBY
CASS COUNTY RECORDER

BY SR Dep


On 3/14/2013, found a(n): 1/2" Iron Pipe With Plastic Cap
Stamped "RLS 9672" up 0.5'.

- left monument as found
- lowered monument
- removed monument (explain)
- raised monument

On _____, set a(n): _____


See "Statement of Evidence" for further details (on back)

(reserved for recording data)



20

29



"SKETCH OF REFERENCE TIES" (not to scale - bearings are magnetic)

Ties are measured to center of monument unless otherwise noted.

UNITS = Metric English

CASS COUNTY SOUTH COORDINATES

Northing: 346934.648

Easting: 617177.168

NAD 83/2007 Adjustment.
Obtained by RTK GPS observations.

I hereby certify that this survey, plan, or report was prepared by me or under my direct supervision, and that I am a duly Licensed Land Surveyor under the laws of the State of Minnesota.

signature

4-30-2013
date

Jarrett M. Leas, Minnesota License No. 42619

Page 1 of 2 A000596810



Statement of Evidence

North Quarter corner of Section 29, Township 139 North, Range 26 West, 5th Principal Meridian.

- 1863 The US General Land Office, in notes of the subdivision of Township 139 North, Range 26 West, set a post for the original corner and referenced it as follows:
14" W. Pine N 30° W 14 links 20" Y. Pine S 6° E 32 links
Said records are on file with the Minnesota Historical Society, St. Paul, Minnesota, copies are filed with the Cass County Surveyor's Office (CCSO).
- 1986 W. Buckler, LS 9672, map on file in the CCSO, indicates subject corner in place.
- 1998 The Cass County Land Department found the subject corner to be in place in excellent condition.
- 2013 Jarrett Leas, LS 42619, March 2013, in correspondence with Mr. Buckler by telephone, determined the corner was set by Mr. Buckler circa mid 1980's.
- 2013 A KLJ survey crew found a ½" iron pipe up 0.5', and is witnessed with the found ties shown on the front of this certificate. Jarrett Leas, RLS #42619, after analysis of record and survey information accepts this monument as the correct perpetuation of the corner.