

OFFICE OF THE COUNTY RECORDER CASS COUNTY, MINNESOTA CERTIFIED, FILED, AND/OR **RECORDED ON** 

8/9/2017 11:05:14 AM AS DOC #: A000633292

PAGES: REC FEES: 0.00

KATHRYN M. NORBY CASS COUNTY RECORDER

BY\_SR\_\_\_Dep TX#: 140334

Twp <u>136</u> Rge <u>31</u> Index No.\_\_ CERTIFICATE OF LOCATION OF GOVERNMENT CORNER Northeast corner of Section 30 , Township 136 N. , Range 31 W. , State of Minnesota, County of Cass At the corner location shown on the sketch: On 25 Feb. 1999 found a 7/8 inch ODIP, capped RLS 17008, 34 feet  $\pm$  South of centerline County Road No. 24 ☐ lowered monument removed monument (explain) placed SKETCH OF REFERENCE TIES Monument NOT TO SCALE Chisled X on 24 inch Concrete Culvert Hay Field roperty Corner SECTION 19 SECTION 20 RLS 17008 is marked Centerline of paved road CSAH No. 24 # 34 S 80. E 7/8 inch pipe RLS 17008 46.60 feet Chisled X on 24 inch Concrete Culvert Hay Field SECTION 29 SECTION 30 iron pipe 16d duplex nail up 1.0 feet in W side of 6 inch Willow NOTE: All bearings are true Statement of evidence relative to this corner location is on the back of this page. I hereby certify that this survey, plan or report was prepared by me or under my direct supervision and that I am a duly Licensed Land Surveyor under the laws of the State of Mingesota.

Terry L. Freeman, Cass County Surveyor

MN License No. 21367



A000633292

## Index No. R.0-05.0

## Statement of Evidence

Northeast corner of Section 30, Township 136 North, Range 31 West, 5th Principal Meridian.

R. Cronk, General Land Office (GLO) Deputy Surveyor in the notes of the subdivision of Township 136 North. Aug. 1870

Range 31 West, set a post for the original corner and referenced it as follows: 7" Tam N 40° E 8" Tam

12 links (7.92 feet) N 49 1/2° W 8 links (5.28 feet) 9" Tam 6" Tam S 18° E 16 links (10.56 feet) S 21° W 28 links (18.48 feet)

Said records are on file with the Minnesota Historical Society, St. Paul, Minnesota, copies are filed with the Cass County Highway Department, Surveyor's Office (CCHD/SO).

W.H. Hallett, Surveyors Report, Certificate image 5249, on file in the CCHD/SO, road survey indicates the Oct. 1903 subject corner position in a road.

H.F. Baldwin, Survey Record #290, Book B, page 250, Curo Book 67, page 8-9 and Curo Book 185, page 2, on June file in the CCHD/SO, states "old corner post which natives say was set by surveyor Hallett from U.S. bearing trees, 1916 checks for course and distance with two old stumps which are badly burned and show no scribe marks".

H.F. Baldwin, Survey Record #290, Book B, page 255 and Curo Book 67, page 38, on file in the CCHD/SO, states July 1916 "go to Sec. Cor. 19-20-29-30-136-31 where all U.S. B.Ts are gone we establish sec. Cor. by chainage E. & W.", "Here we drive a wagon spoke with tack for true corner" and witness as follows:

R.P. Stake NE 46.70 feet R.P. Stake NW

46.70 feet R.P. Stake R.P. Stake SE 46.70 feet SW 46.70 feet.

1985 Cass County Highway Department (CCHD), S.A.P. 11-624-04, on file in the CCHD, plan indicates corner at culvert, 32 feet, more or less, south of new centerline, at Station 200+04.28.

June D.S. Landecker, LS 17008, Certificate of Survey for Mcallister, copy on file in the CCHD/SO, indicates monument 1998 found south of the centerline of State Aid Highway No. 24.

B. Hippen and C. Loe, technicians, records of the CCHD/SO, found 7/8 inch outside diameter iron pipe, capped Feb. 1999

RLS 17008, 34 feet, more, or less, South of centerline County Road #24 and witnessed as follows: 6" Willow S 16° E

106.16 feet 24" RCP N 30° E 86.01 feet 24" RCP Iron Pipe South 67.13 feet S 80° E 45 60 feet

R.L. Kovanen, LS 16459, Certificate of Survey for Land Department, on file in the CCHD/SO, indicates an iron Sept. 2000 monument found at the subject corner.

B. Hippen and T. Anderson, technicians, records of the CCHD/SO, found 7/8 inch outside diameter iron pipe. Oct. capped RLS 17008, 34 feet, more, or less, South of centerline County Road #24 witnesses in good condition, 2002 located with Global Positioning System (GPS).

July B. Hippen, technician, records of the CCHD/SO, found 7/8 inch outside diameter iron pipe, capped RLS 17008, 2016 34 feet, more, or less, south of centerline County Road #24, 1999 witnesses in good condition.

The monument, recovered and established references for the position are shown on the face of this document.

Analysis of the recovered record data, field evidence and survey measurements, indicates that the monument recovered by the CCHD/SO in 2016 is the accepted location of this corner.

**County Coordinates (Cass County South)** Northing 251587.97 Easting 460166.81