


T. 140 R. 30 M. 5TH Coordinates: X \_\_\_\_\_ Y \_\_\_\_\_  
MC# 4 Corner common to sections LAND 6-140-29



EXISTING SURVEYS

Original Government Survey

Year surveyed 1865  
Original monument POST

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

Species	<u>ASPEN</u>	<u>B.C. PINE</u>	Trees	_____
Diameter	<u>8"</u>	<u>5"</u>	_____	_____
Bearing	<u>N 29 1/2 W</u>	<u>S 56 E</u>	_____	_____
Distance	<u>62 LKS</u>	<u>108 LKS</u>	_____	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1916 By E. B. HORST  
Location filed COUNTY BOOK 8 P. 554-558  
Monument SET 2 1/2 x 48" LIM. CAPPED.  
also on microfilm - roll 105 BK 61 P. 147

Evidence of Subsequent Corner Restoration

Year of search 1925 By John Greene  
Microfilm - Roll 105 CURA NOTES BK - Muscat A  
Capped iron monument  
Ranch

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

D, E - 25

Subsequent Corner Restoration

Year surveyed \_\_\_\_\_ By \_\_\_\_\_  
Location filed \_\_\_\_\_  
Monument \_\_\_\_\_

Evidence of Subsequent Corner Restoration Found

Year of search 1999 By CCSO  
Fd. in place 1 3/4" ADIP down 0.5' in poor condition.  
Located 23' due East to E 121, Due South 66' to Webb Lk., and 48' due North to E 121.

T.W. Oak N 60° W 18.80'  
P. Pole N 15° E 73.75'