


T. 141 R. 27 M. 5TH Coordinates: X _____ Y _____
NE 17 Corner common to sections 8, 9, 16, 17



EXISTING SURVEYS

Original Government Survey
 Year surveyed 1874
 Original monument POST

Species	Bearing	Tree	Distance
<u>TAM.</u>	<u>TAM.</u>	<u>TAM.</u>	<u>CEGAR</u>
<u>10"</u>	<u>14"</u>	<u>8"</u>	<u>7"</u>
<u>S40E</u>	<u>S56W</u>	<u>N57W</u>	<u>S48E</u>
<u>8 LKS</u>	<u>16 LKS</u>	<u>17 LKS</u>	<u>8 LKS</u>

Original Evidence Found
 Year of search _____ By _____
 Monument found _____

Original Bearing Trees Found

Species	Diameter	Bearing	Distance
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____
_____	_____	_____	_____

O = Corner

Subsequent Corner Restoration

Year surveyed 1919 By GLD
 Location filed SECRETARY OF STATE
 Monument FND 2" I.P. SET BY CO. SURVEYOR FROM
ORIG. BITS, CORNER IN ROAD. SET 2x36" I.P. W/
BRASS CAP 36" IN GROUND. 714IN R21W
B.B. DESTROYED IN BUILDING OF E-W ROAD 58 | 59

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>CEGAR</u>	<u>8"</u>	<u>N29-30E</u>	<u>111 LKS</u>
<u>CEGAR</u>	<u>12"</u>	<u>S14E</u>	<u>51 LKS</u>
<u>CEGAR</u>	<u>6"</u>	<u>S27-30W</u>	<u>63 LKS</u>
<u>CEGAR</u>	<u>10"</u>	<u>N8W</u>	<u>72 LKS</u>

Evidence of Subsequent Corner Restoration

Year of search 1982 By Gary Stevenson
Corner Certificate
in 1980 G.Kreuzer - USFS End County capel iron and
GLD iron - cap missing and remains of 1919 BITS
NE, SE and NW - replaced irons with 2"
I.P. W/ brass cap - set old irons alongside

Bearing Trees, Reference Objects

Species	Diameter	Bearing	Distance
<u>Cedar</u>	<u>10"</u>	<u>N29E</u>	<u>64.50'</u>
<u>Ash</u>	<u>8"</u>	<u>S9E</u>	<u>49.30'</u>
<u>Ash</u>	<u>5"</u>	<u>S29W</u>	<u>40.60'</u>
<u>Cedar</u>	<u>5"</u>	<u>N2W</u>	<u>24.80'</u>

Subsequent Corner Restoration

Year surveyed _____ By _____
 Location filed _____
 Monument _____

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
Certificate - Gary Stevenson - Filed by USFS 1984
Doc # 279230 dated 1982

Remonumentation certificate prepared _____
Filed at _____

By _____
Date _____