


T. 143 R. 25 M. 5TH Coordinates: X _____ Y _____
E 1/4 32 Corner common to sections 32, 33



○ = Corner

EXISTING SURVEYS

Original Government Survey

Year surveyed 1872
Original monument Post

Original Evidence Found

Year of search _____ By _____
Monument found _____

Bearing Trees

Species	<u>BIRCH</u>	<u>BIRCH</u>	_____
Diameter	<u>8"</u>	<u>8"</u>	_____
Bearing	<u>N 80 E</u>	<u>S 39 W</u>	_____
Distance	<u>17 LKS</u>	<u>11 LKS</u>	_____

Original Bearing Trees Found

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Subsequent Corner Restoration

Year surveyed 1924 By J. H. FLYNN
Location filed COUNTY BOOK 'D' P. 132
Monument Two old Govt B.T.: 8" BIRCH N 80 E 11.22'
FALLS IN WAGON RUT - SET POST 2' EAST. SET
2 WITNESS POSTS 6' X 6' X 7' EAST AND WEST 33'

Evidence of Subsequent Corner Restoration

Year of search 1976 By BLM
Found 6" CONCRETE POST W/ BRONZE CAP T143N R25W
1/4
532/533
1964
RLS. NO. 6807

Bearing Trees, Reference Objects

Species	_____	_____	_____
Diameter	_____	_____	_____
Bearing	_____	_____	_____
Distance	_____	_____	_____

Bearing Trees, Reference Objects

<u>MAPLE</u>	<u>OAK</u>	<u>MAPLE</u>	<u>STEEL SIGN POST</u>
<u>8"</u>	<u>5"</u>	<u>5"</u>	<u>54-2 & 54-4</u>
<u>N 64 E</u>	<u>S 17 W</u>	<u>N 15 W</u>	<u>WEST</u>
<u>63 LKS</u>	<u>62 LKS</u>	<u>57 LKS</u>	<u>17 1/2 LKS</u>

USFS TIES

X-9

Subsequent Corner Restoration

Year surveyed 1960 By DNR-Engineering
Location filed Map notes in file
Monument found 2 wood post set about 66.5'
apart. Appears that 1/4 cor should be
between them

Evidence of Subsequent Corner Restoration Found

Year of search _____ By _____
CERTIFICATE - OKERMAN - 1964
Set 6" x 60" cylindrical concrete
monument with 3" stamped bronze
tablet.
5" Maple N15W 37.7'
OAK 5" S17W 41.1'
8" Maple N41E 41.8'

1936 CCC A. Jager found cedar post.

1978 G. Stevenson found Conc. cyl.

1982 USFS K. Whitehorn & G. Kosenko
found conc. cyl. and witnessed as
follows:

4" R. Maple S36°E, 29.73'

10/2001 Landecker & Assoc found
Conc. cyl. and USFS 1964 & 1982
witnesses and added:
Sign Posts North, 1.0' and South, 4.2'

Remonumentation certificate prepared _____
Filed at CCRO document #461719

By RLS 17008
Date 1/29/03