


Index No. A 13

CASS COUNTY LAND CORNER RECORD

T. 143 R. 28 M. 574 Coordinates: X NE 4 Y 3, 4 AND 33, 34 - 144-28  
Corner common to sections



EXISTING SURVEYS

Original Government Survey

Year surveyed 1873  
Original monument lost

Original Evidence Found

Year of search \_\_\_\_\_ By \_\_\_\_\_  
Monument found \_\_\_\_\_

|          | Bearing Trees |                    |                 |                    |
|----------|---------------|--------------------|-----------------|--------------------|
| Species  | <u>Linden</u> | <u>Sugar Maple</u> | <u>Basswood</u> | <u>Sugar Maple</u> |
| Diameter | <u>24"</u>    | <u>8"</u>          | <u>10"</u>      | <u>20"</u>         |
| Bearing  | <u>N3W</u>    | <u>S21E</u>        | <u>S28W</u>     | <u>N24W</u>        |
| Distance | <u>20LKS</u>  | <u>20LKS</u>       | <u>34LKS</u>    | <u>10LKS</u>       |

Original Bearing Trees Found

|          |       |       |       |       |
|----------|-------|-------|-------|-------|
| Species  | _____ | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ | _____ |

Subsequent Corner Restoration

Year surveyed 1915 By E.B. HORST  
Location filed COUNTY BOOK "C" P. 276  
Monument IND FROM ROAD SET 2" X 48" I.M. W/ CAP  
1916, E.B. HORST, BOOK "C" P. 556 FND CORNER  
1916 - A. NEWAK - microfilm - roll 105 BK 548 P. 74  
Fnd 2" capped pipe well driven into ground

Evidence of Subsequent Corner Restoration

Year of search 1964 By R.F. SCHNEIDER  
BOOK D, P. 432 IRON PIPE - TIES (NEW)  
1915 - also on microfilm - roll 115 BK 71 P. 30  
P. 64 set 2" X 48" I.M.

Bearing Trees, Reference Objects

|          |       |       |       |
|----------|-------|-------|-------|
| Species  | _____ | _____ | _____ |
| Diameter | _____ | _____ | _____ |
| Bearing  | _____ | _____ | _____ |
| Distance | _____ | _____ | _____ |

Bearing Trees, Reference Objects

|                  |                |                          |
|------------------|----------------|--------------------------|
| <u>SPRUCE</u>    | <u>SPRUCE</u>  | <u>U.S.C. &amp; G.S.</u> |
| <u>14"</u>       | <u>15"</u>     | <u>12. Mon.</u>          |
| <u>516-20W</u>   | <u>N52-45E</u> | <u>547W</u>              |
| <u>39.7'</u>     | <u>145.1'</u>  | <u>20.1'</u>             |
| <u>1964 ties</u> |                |                          |

A-13

Subsequent Corner Restoration

Year surveyed 1974 By Co. Hwt Dept  
Location filed Co. RD # 8  
Monument I.P. in place

Evidence of Subsequent Corner Restoration Found

Year of search July 2005 By T. Freeman #21367  
Cert. of Survey shows monument found

1959 - Co Hwt Dept - Co RD 8 SP11-615-01

I.P.

5/24/2000

LANECKER & ASSOC. SET IP FROM  
FOUND BT'S  
USC & GS ~~BAZMK~~ 547°W 20.1  
PK IN SPRUCE STUMP 516°20'W 39.7  
FOUND 3/8" REBAR 2.45' EAST OF  
ESTABLISHED POSITION

Remonumentation certificate prepared \_\_\_\_\_

By \_\_\_\_\_

Filed at \_\_\_\_\_

Date \_\_\_\_\_