

U. S. Department of Agriculture  
FOREST SERVICE

7-7-8

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 26W 4th P. Mer.  
M.C.

8 17 Corner common to Sections  
and

Corner consists of a 2" iron pipe inground (not) in place


State condition Good

Dimensions above ground 2" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

M. C. S. 17			
B. T.			

Species Aspen

Diameter 16" 1

Bearing S 71° W

Distance 48 links

Do you believe this to be a genuine Land Office Corner? NO

If not, why? County corner

C. Fideldy  
C. Fideldy

(Signature)

Leader

(Title)

2/14/41

(Date)

Corner

Summit road runs within 1 chain of

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears N. 71.1

side of Aspen

tree 16 inches diameter, on the Northeast

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST J 7-8

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 26W 4th P. Mer.

M.C. Corner common to Sections

8, 17, and

Corner consists of a 2" iron pipe in ground

State condition Good

Dimensions above ground 2" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Table with 2 rows (M.C. S.17 and B.T.) and 4 columns for sketching and recording data.

Species Aspen

Diameter 16"

Bearing S71°W

Distance 48 links

Do you believe this to be a genuine Land Office Corner? No

If not, why? County Corner

C. Fideldy

(Signature)

Leader

(Title)

2-14-41

(Date)

-----

-----

-----

-----

-----

-----

-----

-----

-----

-----

corner.

Summit road runs within 1 chain of

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears N. 71° E

side of Aspen

tree 16 inches diameter, on the Northeast

Metal Location Poster is on a Aspen



(Make sketch of topography near Corner)

U. S. Department of Agriculture  
FOREST SERVICE

8-9-8

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 58N R. 26W 4th P. Mer.

M.C. Corner common to Sections  
8 17. and

Corner consists of a Cedar post (not in place)

State condition Good

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

M.C. 1	M.C.		
S. 8	S. 17		
N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? No

If not, why? County corner

C. Fildely  
G. Fedaldy  
(Signature)  
Leader

3/3/41

(Date)

(Title)

16-17 11.42 chains to Mc on Lake  
Follow fence from Sec. Corner 8-9-

Corner again.

Give any further facts which will aid in finding this


1 ft. ~~XXXX~~ chains distant.

from which this Corner bears West

side of Fence post

tree 7 inches diameter, on the West

Metal Location Poster is on a Fence post



(Make sketch of topography near Corner)