

U. S. Department of Agriculture

FOREST SERVICE

E-2

CHIPPEWA NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 25 W 4<sup>th</sup> Mer. N 1/16

Corner common to Sections

6, and 7

Corner consists of a Tamarack post (iron) in place

State condition good

Dimensions above ground 60 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		37	
36		59	
		25	


N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing No B. T.'s

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? The original survey set

no 1/16 corners so I believe it was

set by County.

Arthur Johnson

(Signature)

Squad Foreman


(Title)

11/14/39

(Date)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

# U. S. Department of Agriculture

## FOREST SERVICE

17  
8-7

CHIPPEWA NATIONAL FOREST

### CORNERS OF THE PUBLIC SURVEY

T. 59 N R. 25 W 4 th Mer.

W 1/16 Corner common to Sections  
6, and 7

Corner consists of a Tamarack Post ~~(wood)~~ in place

State condition good

Dimensions above ground 60 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

		S7	
S6		59	
		25	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing NO B. T.'s \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? NO

If not, why? The original survey set  
no 1/16 corners so I believe it was  
set by County.

Arthur Johnson  
(Signature)


Squad Foreman

(Title)

11/14/39

(Date)

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 59 N. R. 25 W. 4 th Mer.