

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

621

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 26 5 Mer.
quarter

Corner common to Sections

11, and 12

Corner consists of a iron pipe (not) in place
in roadway

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

2 S3

1 S3

--

--

BT

BT

--

--

Species	BofG.	BofG.		
Diameter	14"	14"		
Bearing	N58W	S56W		
Distance	1.05	1.40		

Do you believe this to be a genuine Land Office Corner? No
If not, why? I believe this to be a county corner

Walter Haberle

(Signature)

Leader

7/28/39

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on the bearing trees



(Make sketch of topography near Corner)

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

6-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 146 R. 26 5 Mer.

Quarter Corner common to Sections
11, and 12

Corner consists of a iron pipe (not) in place
in ground


State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



BT

BT



Species BofG BofG

Diameter 14" 14"

Bearing N58W S56W

Distance 1.05 1.40

Do you believe this to be a genuine Land Office Corner? No

If not, why? I believe this to be a County corner,

Walter Haberle

(Signature)

Leader

7/28/39

(Date)

(Title)

50

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on the bearing trees



(Make sketch of topography near Corner)