

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

K.L. 9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5<sup>th</sup> Mer.

M. C. Corner common to Sections

17, and 16

Corner consists of a Iron pipe (~~not~~) in place


State condition new

Dimensions above ground 1" - 27" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S-16	S-17		
B.T	B.T		

Species Birch Birch

Diameter 5" 6"

Bearing N-62E N-39W

Distance .03 .04

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

(Signature)

1936

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 R. 27 Mer. 5 25

U. S. Department of Agriculture  
FOREST SERVICE

K.L. 9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 27W 5th Mer.

Meander Corner common to Sections

17, and 16

Corner consists of a Jet P. in place



State condition Jet

Dimensions above ground 1" 27" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of Jet P. is located between sections 17 and 16

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>316</u>	<u>317</u>		
<u>BT</u>	<u>BT</u>		

Species Quercus bicolor

Diameter 5"

Bearing N67°E N39°W

Distance 3 4

Do you believe this to be a genuine Land Office Corner?

If not, why? Yes

(Signature)

(Date)

(Title)

1067 b

U.S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

Corner again

Give any further facts which will aid in finding this


chain distant

from which this corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near corner)

U. S. Department of Agriculture  
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 27 5<sup>th</sup> Mer.

M. C. Corner common to Sections

17, and 16

Corner consists of a Iron pipe (cut) in place



State condition New

Dimensions above ground 1" - 27" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

G-16

S-17

B.T

B.T

Species Birch Birch

Diameter 5" 6"

Bearing N-62E N-39W

Distance .03 .04

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

1936

(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 R. 27 Mer. 5 25