

Form 874-B—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

JK9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 29 W 5th P. Mer.

Meander Corner common to Sections
 _____, _____, 16, and 17

Corner consists of a Tam'c. Post (not) in place

State condition Good

Dimensions above ground 40 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig.	B.T.'s		
-------	--------	--	--

B.T.	B.T.		
------	------	--	--

Species Tam'c. Tam'c.

Diameter 9" 9"

Bearing S79°E S74°W

Distance 8 38

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

John A. Gjelhaug

(Signature)

Jr. Civil Engineer


(Title)

2/1/40

(Date)

Handwritten notes on a grid background, including the word "Corner" and other illegible text.

Corner again.
Give any further facts which will aid in finding this
from which this Corner bears
0° 14' chains distant.
S 80° W
side of
Tree
tree 6 inches diameter, on the West
Metal Location Poster is on a
Twp. C.



(Make sketch of topography near Corner)