

CORNER RESTORATION  
T151N R25W

K&S  
FIELD BOOK

82-0012

BOOK #1

CORNER RESTORATION T151N R25W

#1

T151N R25W

6	5	4	3	2	1					
	8		10		12					
18		16		14						
	20		22		24					
30		28		26						
31	32	33	34	35	36					
1	2	3	4	5	6	7	8	9	10	11

1  
~~1~~ S<sup>1</sup>/<sub>4</sub> CORNER TO SECTION 31 2-3

FROM ~~THE~~ GOV'T RESURVEY OF 1895  
EAST CORRECTED, AT:

49.36 SET ELM POST

BALM OF  
GILEAD 18" N 10°W 78 IKS

BALM OF  
GILEAD 22" N 20°E 65 IKS

6.65 CHAINS WEST TO N<sup>1</sup>/<sub>4</sub> OF  
SECTION 6

11/4/77

STEFAN & STEWART

PULLED CHAIN FROM CLOSING CORNER EAST,  
NO EVIDENCE LOCATED.

2 SECTION CORNER TO SECTIONS 31 & 32

FROM GOV'T. RESURVEY OF 1895

89.36 SET AN ASH POST

FIX 8" N50°W 21 IHS

FIX 7" N70°E 18 IHS

4.63 CHAINS WEST TO SECTION  
CORNER TO SECTIONS 5 & 6

11/3/77

STEFAN & STEWARD

PULLED CHAIN FROM CLOSING CORNER WEST

4.63 CHAINS & FOUND NO EVIDENCE. A

BLAZED & PAINTED LINE EAST-WEST &

A PAINTED UP CORNER AREA ABOUT 1

CHAIN WEST.

3 S<sup>1</sup>/<sub>4</sub> CORNER TO SECTION 32 <sup>2-7</sup>

FROM RESURVEY OF 1895

40.00 SET ELM POST

BIRCH 12" N65°E 22 IKS

BALM OF  
GILLEAD 14" N45°W 20 IKS

3.90 CHAINS WEST TO ~~N~~<sup>1</sup>/<sub>4</sub> OF  
SECTION 5

11/3/77 STEFAN & STEWARD  
PULLED CHAIN FROM CLOSING CORNER, EAST  
& FOUND NO EVIDENCE. WHEN LOCATING  
CLOSING SECTION CORNER WEST WE FELL  
350' SOUTHERLY, WE THEREFORE SEARCHED  
WRONG AREA & SHOULD RETURN.

4 SECTION CORNER TO SECTIONS 2-9  
FROM GOV'T. RESURVEY OF 1895 32433

80.00 SET POST

BIRCH 12" N36°E 22 IKS

FIR 7" N28°W 27 IKS

3.32 CHAINS WEST TO SECTION  
CORNER TO SECTIONS 445.

11/3/77

STEFAN & KRAUSE

PULLED DISTANCE FROM CLOSING CORNER  
TO SECTION 445, BUT FOUND NO EVIDENCE.

5 3/4 CORNER TO SECTION 33 Z-11  
Affidavit 4-30-79

40.00 SET WOOD POST

CEDAR 16" N31°E 53 IKS 34.98'

Fd. 20" CEDAR N35E 35.0' SCRIBE VISIBLE (LEANING)

FIR 6" N35°W 25 IKS 16.5'

Fd. WELL ROTTED STUMP AT BRG. 1/2 DIST.

3.16 CHAINS WEST TO N 1/4  
OF SECTION 4.

NOTES FROM HOOCHING COUNTY-LYKE WOODS

FOUND: CEDAR BT & OAK POST

SET: 1 1/2" X 4' IRON PIPE WITH AL. CAP.

NEW BT: Fd. IRON 1/2" CAP IN PLACE

① CEDAR 9" N18°W 21.2'

② CEDAR 7" N17°E 20.7'

11/7/58

① Fd. 11 CEDAR N18°W 21' SCRIBED 1/4 S33 BT

② Fd. 10 CEDAR N17°E 20.3' SCRIBED 1/4 S33 BT

10-31-77

12/5/78 OLESEN & CREW

STAMPED CAP WITH R.L.S. 12261 AND

MADE 1 NEW BT AS FOLLOWS

CEDAR 10", N50°W, 55.61'

&

SET 8' STEEL SIGN POST EAST .8'

WITH 54-9 STAMPED.

OK  
12/12/78 MGS

CERTIFIED FILED

9-15-81 Steffan

6 SECTION CORNER TO SECTIONS 33 & 34 Z-13

FROM RESURVEY OF 1895

80.00 SET BIRCH POST

BIRCH 12" N36°E 22 IKS

FIX 7" N28°W 27 IKS

3.00 CHAINS WEST TO SECTION  
CORNER TO SECTIONS 344

11/3/77

STEFAN & KRAUSE

A RECENT POST WAS PLACED HERE BY  
KOOCHICHING COUNTY FORESTER IN 1975. IT  
WAS PLACED 3.00 CHAINS FROM CLOSING CORN.  
NO ORIGINAL EVIDENCE LOCATED.



67 S 1/4 TO SECTION 34 Z-15

FROM GOV'T. RESURVEY OF 1895

40.00 SET A BIRCH POST

FIR 10" N66°E 41 IKS

FIR 8" N68°W 45 IKS

2.18 CHAINS WEST TO N 1/4  
OF SECTION 3

11/1/77

KRAUSE

NO EVIDENCE OF THIS CORNER LOCATED.

Chained 2640' E OF STANDARD SEC. COR.

EST. APPROX 1/4 CORNER - PUT FSLP ON 25" ELM

APPROX. CORNER IS 562W 23.0' - FOLLOWED OLD

BLAZED ALL THE WAY TO APPROX. COR. 11-1-77 CRK BG

SET 3' ASH POST 9' HIGH AT APPROX. COR.

8

affidavit 7-30-79

2-17

SECTION CORNER TO SECTIONS 34435

FROM GOV'T RESURVEY OF 1895

80.00 SET A CEDAR POST

CEDAR 8" N76°E 14 IHS 9.24'

Fd. 13" CEDAR WINDFALL AT BRG DIST. WITH SCAR FACING COR.

CEDAR 12" N54°W 28 IHS 18.48'

Fd. 12" CEDAR STUB 60" HIGH WITH ALL SCRIBE VISIBLE

1.95 CHAINS WEST TO SECTION

CORNER TO SECTION 243

NOTES FROM HOOCHICING COUNTY - LYRE WOODS

FOUND: ORIG. POST + 2 CEDAR BT.

SET: 2" X 4 1/2" IRON PIPE WITH AL. CAP.

NEW BT: <sup>ALSO WOOD SQ. POST - POINT</sup> Fd. IRON PIPE IN PLACE

① CEDAR 7" N40°W 64 IHS (42.24')

② CEDAR 9" N65°E 46 1/2 IHS (30.69')

8/11/48

1 Fd. Cedar 10" N32W 42.2' SCRIBE VISIBLE

2 Fd. Cedar 14" N73E 30.7' SCRIBE VISIBLE

12/5/78

OLESEN + CREW

USED PRESENT COUNTY MONUMENT +

STAMPED CAP WITH R.L.S. 12261

MADE THE FOLLOWING NEW BTs

&amp; MADE RECORD OF OTHERS:

OLD BT - CEDAR 11" N35°W, 41.8'

OLD BT - CEDAR 14" N76°W, 30.7'

CEDAR 10" N49°W, 5.97'

ASH 8" N82°E, 25.23'

8' STEEL SIGN POST, WEST 1.7' / 54.9 ATTACHED

CERTIFICATE FILED

9-15-81 by Steffen

9 off Cont 7-30-79 2-19

S 1/4 To SECTION 35

FROM GOVT RESURVEY OF 1895

40.00 SETH CEDAR POST

CEDAR 7" N66E 32 IHS 21.12'

CEDAR 7" N50°W 13 IHS 9.58'

1.82 CHAINS WEST TO N 1/4  
OF SECTION 2

NOTES FROM MOOCHING COUNTY - LYLE WOODS

FOUND: 2 BT 1/2" X ORIG SCRIBED POST

SET: 2" IRON PIPE WITH AL. CAP.

NEW BT:

CEDAR 9" N6°E 63 IHS 41.58'

8/11/48

10/19/77

R. Olesen

Found 1/2" Iron pipe w/ Brass cap  
36" above ground

9" Cedar N46W 9.1' w scribe visible

7" Cedar N62E 19.0' w/scribe visible

9" Cedar N9°E 42.0' w/scribe visible

12/5/78

OLESEN & CREW

STAMPED BRASS CAP R.H.S. 12261

& MADE 2 NEW B.T.'s AS FOLLOWS:

CEDAR 12" N45°E 27.07'

CEDAR 12" N10°W 10.27'

& SET 8' STEEL SIGN POST NEAR PIPE  
WITH 54-9 ATTACHED.

OK

12/14/78  
W/O

10

Aff. Davit 7-30-79

Z-21

SECTION CORNER TO SECTIONS 35 &amp; 36

FROM GOV'T. RESURVEY OF 1895

80.00 SET AN ELM POST

CEDAR 16" N72°E 16 IKS

CEDAR 16" N62°W 19 IKS

1.37 CHAINS WEST TO SECTION  
CORNER COMMON TO SECTION 142

NOTES FROM KOOCHICHING COUNTY - LYLE WOODS

FOUND: 2 CEDAR BT<sub>2</sub> & ORIG POST

SET: 2" X 4 1/2" IRON PIPE WITH AL. CAP.

NEW BT<sub>2</sub> - NONE (OLD ONE GOOD)

8/2/48

10/12/77

STEFAN, KRAUSE, OLESEN

FOUND: 1) 2" X 4 1/2" IRON PIPE WITH BRASS CAP

36" ABOVE GROUND.

2) 18" CEDAR, N72°E, 10.5', FACE OPEN

3) 20" CEDAR WINDFALL WITH SCRIBING  
VISIBLE, COPPED OUT.

12/5/78

OLESEN &amp; CREW

USED COUNTY MONUMENT AS CORNER &amp;

STAMPED SAME, R.H.S. 12261.

MADE 3 NEW BT<sub>2</sub> & SET POST

A FOLLOWS:

OLD BT - CEDAR, 19", N72°E, 10.8'

CEDAR, 21", N45°E, 21.94'

ASH, 6", N20°W, 24.02'

ASH, 6", N40°W, 19.83'

SET 8' STEEL SIGN POST 1.97' EAST WITH  
549 ATTACHED.OK  
MALS

CERTIFICATE FILED

9-15-81

11

affidavit 7-30-79 Z-23

S<sup>1</sup>/<sub>4</sub> To SECTION 36

FROM GOV'T. RESURVEY OF 1895

40.00 SET A SPRUCE POST

SPRUCE 7" N56°E 10 IHS

SEE #4 BELOW

BALM OF  
GILEAD 10" N41°W 50 IHS

SEE #6 BELOW

.70 CHAINS WEST TO N<sup>1</sup>/<sub>4</sub>  
OF SECTION 1

NOTES FROM HOOCHICING COUNTY - LYLE WOODS

FOUND: ORIG. SCRIBED POST &amp; 1 BT

SET: 2" x 4<sup>1</sup>/<sub>2</sub>' IRON PIPE WITH AL. CAP

NEW BT:

ASH 12" N4°E 48<sup>1</sup>/<sub>2</sub> IHS (32.01')

Found:

10/17/77 STEFAN

KRAUST &amp;

ORESEN

1) 2" x 4<sup>1</sup>/<sub>2</sub>' IRON PIPE WITH BRASS CAP,

2) 14" BLACK ASH, SCRIBED, N15°E, 32.5'

3) 17" BALM, OPEN FACE ROTTED OUT  
N41°W, 33.0'

4) 8-10" SPRUCE STUMP, N56°E, 6.6'

12/6/78

ORESEN &amp; CREW

STAMPED BRASS CAP, PLS 12261 &amp;

MADE 3 NEW BTs AS FOLLOWS:

ORIG BT BALM OF G 17", N41°W, 32.4'

OLD BT ASH 14", N15°W, 48.71'

ASH 7", N33°E, 36.1'

ASH 10", N14°W, 48.1'

ASH 4", N43°W, 38.3'

SET 8' STEEL SIGN POST 1.4' EAST / 54-9.

10/17/77  
STEFAN  
KRAUST &  
ORESEN

CERTIFICATE FILED

9-15-81

Remainder of  
Book -

Blank  
Pages