

BUSY 4 - NE 1/4  
 SEC. 30, T. 141 N., R. 31 W.

022072

HANSON

(SS)	T @ 2, BS 1 (615.98)		FD EP
3	X 352-17.51	M) 352-17.54	UP 2"
	X 352-17.56		RLS 21367
		HD 302.64	
(SS)	T @ 3, BS 2		FD EP
4	X 344-27.05	M) 344-27.04	UP
	X 344-27.03		RLS 21367
		HD 201.96	
(SS)	T @ 4, BS 2		FD EP
5	X 332-13.19	M) 332-13.20	△
	X 332-13.21		
		HD 311.66	
(SS)	T @ 1, BS 2		FD EP
6	X 256-27.31	M) 256-27.34	UP 5"
	X 256-27.36		
		HD 247.05	
(SS)	T @ 5, BS 2		FD EP
7	X 111-23.36	HD 9.08	UP 5"
8	X 133-00.16	M) 133-00.14	△
	X 133-00.12		
		HD 194.46	

TJ  
 TJ

4-24-02  
 35° APPROX 49


1 - FOUND BRASS CAP (1984) IN CONCRETE CYLINDER  
 (1962)

UP 2'

FOUND 3  
 PINE TOP  
 PICK  
 1 X 2 1/2 IN  
 5/16 IN DIA

TOWARD  
 LAKE

FIELD 1 1/2 TO 3/4  
 10 12 13



RECEIVED  
 #1540  
 MAY - 1 2002  
 COUNTY SURVEYOR