


T143N R25W

# Points

**Project : Leighton Lake**



<b>User name</b>	Administrator	<b>Date &amp; Time</b>	10:35:42 AM 9/30/2003
<b>Coordinate System</b>	Projection from data collector	<b>Zone</b>	Zone from data collector
<b>Project Datum</b>	Datum from data collector		
<b>Vertical Datum</b>		<b>Geoid Model</b>	Minn99 (Geoid99 Conus)
<b>Coordinate Units</b>	US survey feet		
<b>Distance Units</b>	US survey feet		
<b>Height Units</b>	US survey feet		

F/GREG ROBERTSON  
@ KASMA

## Itasca Co. South Coordinates


Point listing

	Name	Northing	Easting	Elevation	Feature Code
	SKUNK MNDOT	164772.890	490695.560	1291.959	BASE
S/4 12 {	53512070	166060.661	487130.655	1289.101	USFS
@ E/4 11 →	FENCE-CL RD	168945.247	484316.350	1288.031	NONE
SE 11 {	53511020	166164.150	484442.571	1296.016	USFS
	53511020 CK	166164.111	484442.577	1296.013	USFS
SE 3 {	53503020	171488.688	479002.968	1295.262	IRON ROD
	53503020 CK	171488.704	479002.992	1295.228	IRON ROD
NE 3 {	54534020	176906.380	479275.033	1300.165	16D TIES
	54534020 CK	176906.432	479274.973	1300.145	16D TIES

High RMS

Back to top

Bob,  
 Could not find E/4 3. May be in shoulder of road - too close to mail boxes. Also w. Pine NW removed when road was rebuilt. N. Pine present.



*Greg*

Point Num	Point Desc	Source (f)	Target (f)	Vertical (f)
1302	14325J.0-23.0	YC: 166060.612 XC: 487130.705	YC: 247610.740 XC: 607274.778	Theta: 0 18 58.40
1403	14325J.021.0	YC: 166164.150 XC: 484445.571	YC: 247697.674 XC: 604589.060	Theta: 0 18 29.91
1003	14325E.0-17.0	YC: 171488.688 XC: 479002.968	YC: 252988.449 XC: 599113.648	Theta: 0 17 32.09
303	14325A.0-17.0	YC: 176906.380 XC: 479275.033	YC: 258407.714 XC: 599352.207	Theta: 0 17 34.92

1 meter = 3.280833333 (39.37/12) U.S. Survey feet