




# Work Map Section 6 & 7-133-29



Section 6-133-29



Section 7-133-29



● Indicates iron monument found  
 ○ Indicates iron monument not found, marked RLS 22888  
 Orientation of this bearing system is the North American Datum of 1983.



KLD

#5261